

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: AIG	DATE	: 18-May-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: Asher	VEHICLE NO	: GBC784G
ADDRESS	:	MODEL	: TOYOTA HIACE
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE :			
POLICY NO. :			
<u>ACCIDENT DETAILS</u>		DATE :	
		TIME :	
THIRD PARTY REQUESTOR / CONTACT : XIONG 8121 0478			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 458.00	\$ 458.00
2	FRONT BUMPER SIDE RETAINER <i>LH 2nd</i>	1	\$ 178.00	\$ 178.00
3	FRONT BUMPER FOG LAMP COVER LH <i>Replaced</i>	1	\$ 154.00	\$ 154.00
4	FRONT BUMPER LOWER GRILLE <i>Replaced</i>	1	\$ 120.00	\$ 120.00
5	FRONT BUMPER REINFORMENT TOP <i>Replaced</i>	1	\$ 289.00	\$ 289.00
6	FRONT BUMPER REINFORMENT LOWER <i>Replaced</i>	1	\$ 548.00	\$ 548.00
7	FRONT BUMPER REINFORMENT BRACKET <i>Replaced</i>	1	\$ 215.00	\$ 215.00
8	FRONT CORNER PANEL LH <i>Replaced</i>	1	\$ 189.00	\$ 189.00
9	CENTRE GRILLE <i>Replaced</i>	1	\$ 384.00	\$ 384.00
10	CENTRE GRILLE BASE <i>Replaced</i>	1	\$ 214.00	\$ 214.00
11	SIDE MIRROR LH <i>Replaced</i>	1	\$ 389.00	\$ 389.00
12	HEADLAMP LH <i>Replaced</i>	1	\$ 450.00	\$ 450.00

13	HEADLAMP BRACKET <i>could</i>	1	\$ 41.00	\$ 41.00	✓
14	FRONT WINDSCREEN RUBBER <i>Neu</i>	1	\$ 254.00	\$ 254.00	+
15	BONNET <i>Reps</i>	1	\$ 598.00	\$ 598.00	+
16	BONNET HINGE <i>Neu</i>	1	\$ 154.00	\$ 154.00	+
17	BONNET LOGO <i>Neu</i>	1	\$ 89.00	\$ 89.00	✓
18	BONNET LOCK <i>Neu</i>	1	\$ 168.00	\$ 168.00	+
19	WIREHARNES <i>Neu</i>	1	\$ 584.00	\$ 584.00	+
20	FRONT DOOR LH <i>Dented</i>	1	\$ 1,208.00	\$ 1,208.00	✓
21	FRONT DOOR INNER TRIM <i>Neu</i>	1	\$ 445.00	\$ 445.00	+
22	FRONT DOOR FRIM RUBBER <i>Neu</i>	1	\$ 68.00	\$ 68.00	+
23	FRONT DOOR WEATHERSTRIP <i>Neu</i>	1	\$ 154.00	\$ 154.00	+
24	FRONT DOOR CONNER RUBBER <i>Neu</i>	1	\$ 115.00	\$ 115.00	+
25	FRONT DOOR HINGE <i>Neu</i>	1	\$ 156.00	\$ 156.00	+
26	FRONT DOOR STEP GARNISH <i>cat</i>	1	\$ 189.00	\$ 189.00	✓
27	FRONT DOOR STEP PANEL <i>Neu</i>	1	\$ 511.00	\$ 511.00	+
28	FRONT DOOR PILLER (INNER) <i>Reps</i>	1	\$ 548.00	\$ 548.00	+
29	FRONT DOOR PILLER (OUTER) <i>Dented</i>	1	\$ 554.00	\$ 554.00	✓

3781

283575

TOTAL PRICE \$ 9,424.00

LESS 25% \$ 2,356.00

SUB TOTAL PRICE \$ 7,068.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Neu</i>	1	\$ 50.00	\$ 50.00	+
2	FRONT BUMPER CLIP <i>Neu</i>	1	\$ 50.00	\$ 50.00	30. +
3	FRONT WINDSCREEN SEALANT <i>3.4</i>	1	\$ 60.00	\$ 60.00	+
4	FRONT WINDSCREEN INNER SEAL <i>3.4</i>	1	\$ 60.00	\$ 60.00	+
5	DASHBOARD CLIPS SET <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
6	FRONT DOOR SEALANT <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
7	FRONT DOOR INNER TRIM CLIPS <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
8	FRONT DOOR PILLER (INNER) SEALANT <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
9	FRONT DOOR PILLER (OUTER) SEALANT <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
10	COMPANY STICKER <i>Neu</i>	1	\$ 50.00	\$ 50.00	20. +
11	BRAKE OIL <i>Neu</i>	1	\$ 50.00	\$ 50.00	+

TOTAL \$ 620.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,500.00	900	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,200.00	700	
3	TUFF COAT	\$200.00	50	
4	WIRING CHECK	\$150.00	30	
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$400.00	80	
6	TRANSFER FRONT DOOR MECHANISM LH	\$ 150.00	80	
7	REMOVE AND REFIX AIRCON COOLING COIL AND REFILL AIRCON GAS	\$250.00	x	
8	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	\$450.00	x 220	
9	REFOCUS HEADLAMP BEAM	\$120.00	x	
10	REMOVE AND REFIX FRONT WINDSCREEN	\$150.00	x	

2060

TOTAL

\$4,570.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,088.00
TOTAL LABOUR COST : \$ 4,570.00
TOTAL REPAIR COST : \$ 12,258.00

APPROVED DETAILS

EXCESS :
NO. OF DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
w/p 79/05/20
told: 4945/75
h/s: 3.9/k

06 Days.

3.9/k Confirmed