

YEW BOO SPRAY PAINT CO.

10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 76, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 o. : 64534177 Fax No. : 64593724
 il : limyewboo@singnet.com.sg
 site : www.limyewboo.com.sg
 s. Reg. No. : 200514/00L

G INSURANCE (SINGAPORE) PTE LTD
 AFFLES QUAY #24-01
 S LEONG BUILDING SINGAPORE 048581

tion : Motor Claim Department
 act : 62209644 Fax No. : 62257402

Estimate : TP20/021

Date : 15/06/2020
 Vehicle Num. : SKP 1129S
 Make/Model : TOYOTA ALPHARD-2009
 Chassis/Eng# : ANG208021239/2AZC497018
 Accident Date : 15/05/2020
 Claim No. :
 Reference : LYB/SKP1129S/MSIG/tp/sl
 Policy No. :

Not Authorised
Limy & FOSDI
Resurvey After Paint
6 days

Quantity	Particular	Unit Price	Amount S\$
	LIST ITEMS :		
1	FRONT BUMPER		
1	FRONT BUMPER TOWING HOOK COVER		
2	FRONT BUMPER RETAINER		
1	FRONT BUMPER BEAM		
1	FRONT BUMPER SPONGE		
1	FRONT BUMPER LOWER GRILLE		
2	FRONT SENSOR		
2	FRONT SENSOR HOUSING		
1	FRONT FOG LAMP/LH		
1	FRONT GRILLE		
1	FRONT EMBLEM		
1	FRONT HEADLAMP ASSY/LH		
1	FRONT HEADLAMP CLIPS		
1	FRONT FENDER/LH		
1	FRONT FENDER INNER SHIELD/LH		
1 SET	FRONT FENDER INNER SHIELD CLIPS		
1	FRONT FENDER MLDG/LH		
1	FRONT W/SCREEN SIDE GARNISH/ LH		
1	FRONT BONNET		
2	FRONT DOOR HINGES/LH		
1	FRONT RIM/LH		
1	FRONT KNUKKLE ARM/LH		
1	FRONT KNUKKLE BEARING/LH		
1	FRONT LOWER ARM/LH		

also di's 115.00

nd 419.70
 19.10

mg cm

<i>Bt</i>	1,280.90	✓
<i>Sh</i>	49.80	x
	230.00	✓
<i>R</i>	318.70	x
<i>Sh</i>	60.00	x
<i>Sh</i>	220.50	x
	839.40	✓
<i>Sh</i>	38.20	✓
<i>Sh</i>	412.00	x
<i>Di's</i>	810.50	—
<i>Sh</i>	120.50	—
	3,108.85	✓
<i>Sh</i>	12.30	✓
<i>Bt</i>	689.10	✓
<i>cm</i>	175.90	✓
<i>Sh</i>	12.00	✓
<i>Sh</i>	230.60	x
<i>Sh</i>	249.70	x
<i>R</i>	490.50	x
<i>R</i>	71.80	x
<i>nd</i>	850.00	✓
<i>Bt</i>	570.00	✓
<i>Sh</i>	350.50	✓
<i>Di's</i>	435.00	✓

CONTINUE / ...

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

IM YEW BOO SPRAY PAINT CO.

K 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721

No. : 64534177 Fax No. : 64593724

Mail : limyewboo@singnet.com.sg

Website : www.limyewboo.com.sg

Bus. Reg. No. : 200514/00L

SIG INSURANCE (SINGAPORE) PTE LTD
 RAFFLES QUAY #24-01
 NG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department

Contact : 62209644 Fax No. : 62257402

Estimate : TP20/021

Date : 15/06/2020
 Vehicle Num. : SKP 1129S
 Make/Model : TOYOTA ALPHARD-2009
 Chassis/Eng# : ANG208021239/2AZC497018
 Accident Date : 15/05/2020
 Claim No. :
 Reference : LYB/SKP1129S/MSIG/tp/sl
 Policy No. :

Quantity	Particular	Unit Price	Amount S\$
1	FRONT SHOCK ABSORBER/LH		485.00 ✓
1	FRONT STABILIZER LINK/LH		148.50 x
1	FRONT TEI ROD END/LH		126.70 ✓
	List Total S\$:		12,386.95
	20.00% Discount S\$:		2,477.39
	25%		9,909.56
	LABOUR :		
	TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS	120.00	301
	TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION	55.00	201
	LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS	80.00	601
	TO COMPUTERISE WHEEL ALIGNMENT	120.00	601
	TO REMOVE & REPLACE LH FRT ¼ GLASS TO FACILITATE REPAIR	80.00	x
	TO REMOVE & REPLACED RIM	80.00	201
	LABOUR CHARGE FOR REPLACING UNDERCARRIAGE ITEMS	280.00	2001
	TO RE-SET ABS SYSTEM & EARSE REGISTERED FAULT	120.00	801

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department

Contact : 62209644 Fax No. : 62257402

Estimate : TP20/021

Date : 15/06/2020
 Vehicle Num. : SKP 1129S
 Make/Model : TOYOTA ALPHARD-2009
 Chassis/Eng# : ANG208021239/2AZC497018
 Accident Date : 15/05/2020
 Claim No. :
 Reference : LYB/SKP1129S/MSIG/tp/si
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB		nn 350.00 X
		TO REPAIR, PANEL BEAT, RE-ALIGN ON LEFT FRT AFFECTED DOOR, FRT AFFECTED PANEL & LABOUR TO REPLACE THE ABOVE MENTIONED PARTS		1,000.00 500l
		TO PUTTY, PRIMER & SPRAY PAINT ON FRT BONNET, FRT BUMPER, FRT SENSOR, FRT FENDER, FRT FENDER PROTECTOR, FRT DOOR, FRT DOOR PROTECTOR USING 2K PEARL WHITE.		1,300.00 660l
		Labour Total S\$:		3,585.00
E. & O.E.			Total S\$:	13,494.56 =====


 for LIM YEW BOO SPRAY PAINT CO.