

China
LKK
Konnath

辉陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

5/05/2020

wner: ZACH TRANSPORTATION

ESTIMATE TO REPAIR TOYOTA CHR 1.8 - SLV2649H

front bumper	946.50	CM \$	974.45	✓
front bumper RH side retainer		D.I \$	133.35	✓
front bumper RH side garnish	255	D.I \$	374.45	✓
front bumper clip @\$5.00		M \$	100.00	✓
front bumper grille	154.70	D.I \$	258.25	✓
front bumper sponge	95.20	CM \$	181.50	✓
front bumper lower cover		S \$	182.50	X
front bumper lower lid	410	Ref \$	680.00	✓
front centre grille base		S \$	481.50	X
front wiper spare tank		Ref \$	281.50	✓
front RH headlamp (LED)	2327.50	CM \$	2,821.40	✓
front RH fender		R \$	781.90	X
front RH fender "HYBRID" emblem		M \$	121.50	✓
front RH fender protector	210	Ref \$	374.20	✓
front RH fender inner shield	272.60	CM / D.I \$	381.90	✓
front RH fender inner shield clip @\$5.00		M \$	50.00	✓
			\$ 8,178.40	
			\$ 2,044.60	
			\$ 6,133.80	
less 25%				
alignment			\$ 60.00	✓
tuffkote		na	\$ 100.00	X
wiring			\$ 100.00	201
spray painting			\$ 800.00	4501
labour charges			\$ 800.00	4001
Total			\$ 7,993.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Hui Yang Motor Pte. Ltd.