

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

311

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB214U

Ref. No

TAX/04/17/2181

Reg. Date

05/11/2014

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

SON YEW SAN

Type of Accident

HEAD TO SIDE

Date / Time of Accident

27/04/2017 12:15:00 PM

Accident Reported Date / Time :

27/04/2017 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No

000024089273

Special Instruction to ARC, if any :

SLB6230K / AXA

Prepared Date

: 27/04/2017 02:12:00 PM



Ath Regar pla

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U805752585

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

845.00

0.00

Total Spray Painting Charges

936.00

0.00

Total Material Charges

2,719.18

2.719.18

Other Charges

700.00

0.00

TOTAL

5,200.18

0.00

Lum Sum Total

: 0.00

0.00

No. of Repair Days

6.00

Prepared / Adjusted By

000 Jays

Arc / Surveyor Sing Off Date

: 28/04/2017 09:21:33 AM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 28/04/2017 09:21:30 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Total Labour | 845.00 | 0.00 300 | | | |
|---------------------------|--------------------|-------------------------------------|--|--|--|
| TO REPAIR RH REAR PORTION | 845.00 | 0.00 | | | |
| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable | | | |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable | | | |
|--------------------------------------|--------------------|-------------------------------------|--|--|--|
| TO REPSRAY REAR BUMPER | 378.00 | 0.00 | | | |
| TO RESPRAY REAR FENDER RH | 378.00 | 0.00 | | | |
| TO RESPRAY RIM | 180.00 | 0.00 | | | |
| Total Spray Painting & Panel Beating | 936.00 | 0.00 450 | | | |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION | 80.00 | 0.00 |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00 | 0.00 |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING | 120.00 | 0.00 |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | 120.00 | 0.00 |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00 | 0.00 |
| TO REPLACE SUNDRY PARTS | 100.00 | 0.00 20 |
| TO WASH AND VACUUM | 60.00 | 0.00 😾 |
| Total Other Costs | 700.00 | 0.00 |

TAX/04/17/2181 Page:

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommen d | Surveyor Approved | Photos Attached |
|-----------------|-----------------------------|----------|-------------------------------|-----|--------------------|-----------------|---------------------|----------------------|---------------------------|--------------------|
| 52159- 47905 | | 6505548 | BUMPER REAR | - 1 | 458.60 | 25.00 | 343.95 | Replace | Replace X | Mo |
| 52591- 47021 | | | BUMPER SEAL, RR RH | 1 | 65.70 | 25.00 | 49.27 | Replace | Replace X | No |
| 52575- 47020 | | 6505549 | BUMPER SIDE RETAINER RR/RH | 1 | 94.80 | 25.00 | 71.10 | Replace | Replace X | No |
| | | | SENSOR REVERSE | 1 | 180.00 | 0.00 | 180.00 | Replace | Replace X | - No |
| | | | PIXEL STICKER | 2 | 60.00 | 0.00 | 120.00 | Replace | Replace | No |
| 61604- 47090 | | | FENDER RR/RH | 1 | 766.80 | 25.00 | 575.10 | Replace | Replace λ | Lepair |
| | COMMO N | | SMRT LOGO | 1 | 7.80 | 0.00 | 7.80 | Replace | Replace | No |
| | COMMO N | | STICKER DECAL 6555 8888 | 1 | 21.60 | 0.00 | 21.60 | Replace | Replace | No |
| 65637- 47021 | | 6505480 | FENDER LINER RR/RH | 1 | 141.30 | 25.00 | 105.97 | Replace | Replace \leftthreetimes | No |
| | 6503707 | 6503707 | TYRE | 1 | 126.74 | 0.00 | 126.74 | Replace | Replace | No |
| 42611- 47140 | | 6505658 | WHEEL, DISC | 1 | 1,490.20 | 25.00 | 1,117.65 | Replace | Replace X | No repair |
| | | T | TOTAL MATERIALS | | | | | 2,719.19 | 2,719.18 | |
| | TOTAL MATERIALS(Discounted) | | | | | | | 2,719.18 | 2,719.18 | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|-----------|-----|--------------------|-----------------|---------------------|-----------|-------------------|-------------|
| TOTAL SUPPLEMENTARY MATERIALS | | | | | | | | | |

Kaha 16/14 1 28/4/17