



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TPMS 16.
Celine.

RU11021302

Page No. 1

Vehicle No. SKV4105J HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	TAILGATE <i>Dented</i>		1150.00	✓ 1100
1	TAILGATE HANDLE COVER <i>new</i>		55.00	+
1	TAILGATE UPPER GARNISH <i>new</i>		353.00	+
2	TAILGATE RUBBER STOPPER @\$6.00 <i>new</i>		12.00	+
1	TAILGATE "VEZEL" EMBLEM <i>new</i>		85.20	45
1	TAILGATE EDGE WEATHERSHIP <i>at</i>		162.30	✓
1	TAILGATE INNER TRIM GARNISH <i>could</i>		330.80	285
1	TAILGATE HONDA LOGO <i>new</i>		81.20	+
1	TAILGATE LOCK <i>changed</i>		220.90	✓
2	TAILGATE DAMPER LH & RH @\$300.00 <i>new</i>		600.00	+
2	REAR TAILGATE LAMP LH & RH @ 445.80 <i>at</i>		891.60	826.40
2	REAR TAILLAMP LH & RH @\$553.20 <i>at</i>		1106.40	921
2	REAR TAILLAMP PANEL LH & RH @\$299.50 <i>Regis</i>		599.00	+
1	REAR BUMPER <i>Deformed</i>		835.00	✓
2	REAR BUMPER SIDE RETAINER LH & RH @\$110.00 <i>new</i>		220.00	70
2	REAR BUMPER SIDE BRACKET LH & RH @\$91.00 <i>new</i>		182.00	+
2	REAR BUMPER REFLECTOR LH & RH @\$160.00 <i>new</i>		320.00	+
2	REAR BUMPER CORNER PANEL LH & RH @\$220.00 <i>Regis RH Ref'd</i>		440.00	220
1	REAR END PANEL <i>Dented</i>		643.50	517
1	REAR END PANEL TOP GARNISH <i>Ref'd</i>		280.00	128
1	REAR SPARE TYRE PANEL <i>Regis</i>		1258.00	+
1	REAR SPARE TYRE BOX LOWER COVER <i>Ref'd</i>		740.90	242.10
1	REAR SPARE TYRE BOX TOP GARNISH <i>Ref'd</i>		330.50	307
1	REAR EXHAUST MOUNTINGS <i>new</i>		5521.52	98.00
1	REAR EXHAUST SILENCE ASSY <i>Regis</i>		717.60	+
2	REAR FENDER INNER TRIM BOARD LH & RH @\$773.00 <i>could</i>		1546.00	736
1	REAR REMOTE CONTROL SENSOR <i>could</i>		158.00	2
	Rear Smart Buzzer <i>could</i> 65 ✓		12918.10	
	u spare tyre panel upper sponge 258 ✓	less	2583.62	20%
			10334.48	
SPECIAL NETT ITEMS				
1 SET	REVERSE SENSOR <i>Changed</i>		280.00	200
1	REAR END PANEL SEALANT <i>new</i>		100.00	80
1	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		80.00	10
1 SET	TAILGATE INNER TRIM CLIPS <i>new</i>		60.00	30
1	REAR WINDSCREEN SEALANTS <i>new</i>		100.00	60
1 SET	REAR BUMPER CLIPS <i>new</i>		80.00	30
Total Parts			11034.48	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-20
Singapore 417807
Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SKV4105J HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	800
3	To remove and refix wiring at damaged areas	200.00	30
4	To perform anti rust treatment on affected areas	180.00	80
5	To remove & refix / replace rear trims, garnish and fitting so as to facilitate repairs as rear compartment	210.00	80
6	To remove and replace reverse sensors and check for proper functions	120.00	50
7	To remove and refix rear tailgate windscreen	150.00	120
8	To remove and replace rear exhaust silencer	250.00	x 2240
9	To remove and refix rear tailgate mechanism	120.00	80
Labour Total :		4230.00	
TOTAL (PARTS & LABOUR) :		15264.48	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/s 19/05/20
06 Page

Total: 8551.52

L/s: 6.8K

(6.8K)