

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 18 May 2020

ASSESSMENT FOR REPAIR: YAMAHA GDR155A (AEROX) - FBQ8256M

Chassis No.:

Engine No.:

Qty	Description	Estimate
1 pc	Front mudguard rear cover	\$75.00 ✓ CRK
1 pc	Front mudguard	\$95.00 ✓ CRK
1 pc	Wheel axle	\$60.00 X SVL
1 pc	Brake disk	\$185.00 X SVL
1 pc	Right fork assy	\$300 \$420.00 ? ✓ DEF
1 pc	Left fork assy	\$300 \$420.00 ? ✓ DEF
1 pc	Steering stem	\$100 \$220.00 ? ✓ DEF
2 pcs	Steering stem bearings @ \$45.00	\$90.00 ? ✓ NEC
1 pc	Centre cover inner body	\$120.00 ? ✓ DEF
1 pc	Centre cover lower	\$140.00 ? ✓ DEF
1 pc	Front cover	\$95.00 ✓ SVL
1 pc	Headlamp lower cover	\$75.00 ? ✓ DEF
1 pc	Left front fairing	\$120 \$150.00 ? ✓ DEF
1 pc	Left front fairing amblems	\$35.00 ? ✓ NEC
1 pc	Right front fairing	\$120 \$150.00 ? ✓ DEF
1 pc	Right front fairing amblems	\$35.00 ? ✓ NEC
1 pc	Top cover front	\$70 \$95.00 ✓ SVL
1 pc	Top cover front amblem	\$20.00 ✓ NEC
1 pc	Top cover rear	\$85.00 ?
Less discount 10%		1,775 \$2,565.00
<u>Special nett items</u>		\$256.50
		1,597.50 \$2,308.50

1 pc	Front sport rim	\$420.00 ? X SVL
1)	Towing charges	\$100.00 X
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00 300
3)	To remove, replace and balance front wheel rim	\$120.00 X SVL
4)	To knock, straighten chassis & body balancing	\$380.00 50 X NN

FORK CARBON
 REPAIR BEATON

- 5) To remove/refit, replace (if damage) check and
6) straighten front fork tubes.
Spray painting

\$180.00 ~~90~~
\$300.00 ~~100~~

Total Estimate

\$4,508.50

Note: The above estimate is subjected to the prevailing GST of 7%

N/A2 LKK

20/5/2020 1500

L13

3 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS



For Bike Production Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 26 May 2020

SUPPLEMENTARY REPAIR: YAMAHA GDR155A (AEROX) - FBQ8256M

Chassis No.:
 Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Left inner black cover	\$85.00 ✓ DEF
1 pc	Right inner black cover	\$85.00 ✓ DEF
1 pc	Headlamp assy	\$250 \$295.00 ✓ CHC
1 pc	Upper inner cover centre	\$120 \$145.00 ✓ SCR
		540 \$610.00
	Less discount 10%	\$61.00
		486 \$549.00
	<u>Special nett items</u>	
	Total Estimate	<u><u>\$549.00</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS \$ 2,315.00
 LESS 10% \$ 2,083.50
 LABOUR \$ 520.00
 \$ 2,603.50
 LESS LIS 20% \$ 2,082.80
 LIS TOTAL \$ 2,100.00 / 3 REPAIR DAYS