

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 21 May 2020

Preliminary Advice

Vehicle No	:	FBQ8256M	Accident Date	:	17/05/2020
Make	:	YAMAHA GDR155A (AEROX)	Policy No.	:	2070032789
Assignment Date	:	19/05/2020	Excess	:	S\$300.00
Date of Inspection	:	20/05/2020	Est. Duration of Repair	:	3.00
Inspection At	:	BIKE PRODUCTION (HQ) NO 610 SERANGOON ROAD SINGAPORE 218216			

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 4,508.50
Revised Amount	:	S\$ 706.50
Check Items (Estimated)	:	S\$ 2,551.50
Total	:	S\$ 3,258.00
Lump Sum Repair		: