

REPAIR ESTIMATE*

VEHICLE NO SHD3362U

DATE 05/15/20 12:00 AM

MAKE :

CHIANG/AIG

MODEL I-40

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|--|------|------------|-------------------|
| 1 | FRONT DOOR LH | | | \$2,256.40 |
| 1 | RH WHEEL HUB COVER | | | \$107.10 |
| | SUB TOTAL | | | \$2,363.50 |
| | 20.00% | | | \$472.70 |
| | DISCOUNTED TOTAL | | | \$1,890.80 |
| | | | | |
| | | | | |
| | FRONT DOOR APP LOGO | | | \$75.00 |
| | FRONT DOOR ADVERTISEMENT | | | \$100.00 |
| | | | | \$175.00 |
| | Labour Charge | | | |
| | Panel Beating | | | \$280.00 |
| | Spray Painting Charge | | | \$400.00 |
| | Transfer door parts | | | \$90.00 |
| | Tuff Kote | | | \$60.00 |
| | TOTAL LABOUR | | | \$830.00 |
| | | | | |
| | ESTIMATE TOTAL | | | \$2,895.80 |
| | | | | |
| | This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will | | | |
| | be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | |
| | | | | |