



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 4627M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR DOOR LH	TO REPAIR SEE LABOUR	912.60	-
1	REAR DOOR FRAME PROTECTIVE STICKER LH	NOT NECESSARY	68.60	-
12	REAR DOOR INNER TRIM CLIPS LH @\$6.20	NOT NECESSARY	74.40	-
1	REAR WHEEL ARCH EXTENSION COVER LH	TO REPAIR SEE LABOUR	180.10	-
	LESS 20% DISCOUNT		-247.14	-
			988.56	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR DOOR PROTECTIVE STICKER LH (SN)	NOT NECESSARY	30.00	-
1	REAR DOOR PROTECTIVE RUBBER LH (SN)	SERVICEABLE	80.00	-
			110.00	-
<b><u>LABOUR</u></b>				
	LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF REAR DOOR LH AND REAR WHEEL ARCH EXTENSION COVER LH.		300.00	200.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR LH.		300.00	300.00
	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	NOT NECESSARY	60.00	-
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR LH INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR LH.	NOT NECESSARY	120.00	-
			780.00	500.00
<b>GRAND TOTAL</b>			<b>1,878.56</b>	<b>500.00</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>				<b>500.00</b>

Report Ref No. CS/FCI20005810/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.