



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/5722/0072/TP/09.19
Date : 28 October 2019

To: Ke Zhenghui
c/o 8 Kaki Bukit Ave 4
#03-47, Premier @ Kaki Bukit
Singapore 415875

VEHICLE APPRAISAL REPORT

Name of Workshop : Lush Automotive Pte Ltd
Place of inspection : 8 Kaki Bukit Ave 4 #03-47, Premier @ Kaki Bukit, Singapore 415875
Date of Assignment : 21 September 2019
Date of Accident : 18 September 2019
Date of Inspection : 21 September 2019

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SMK 72E	Chassis Frame No.	: WDD2050402R020603
Make / Model	: Mercedes Benz C180 Avantgarde	Engine No. (Logcard)	: 27491030266330
Year of Manufacture/Reg	: 2015	Odometer Reading	: 107,933 KM
Colour	: Black		
Class / Type	: Saloon		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Very Good
Paintwork : Very Good
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE


	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	CONTINENTAL 225 / 50 R17	8 mm
Front R	CONTINENTAL 225 / 50 R17	8 mm
Rear L	CONTINENTAL 225 / 50 R17	8 mm
Rear R	CONTINENTAL 225 / 50 R17	8 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	rear bumper	broken	\$ 1,909.00	\$ 1,909.00
2	1 pc	rear bumper lower skirt	broken	\$ 235.75	\$ 235.75
3	1 pc	rear bumper reinforcement	buckled	\$ 701.50	\$ 701.50
4	1 pc	rear bumper tow hook cover	missing	\$ 63.25	\$ 63.25
5	1 pc	rear bumper ctr chrome moulding	broken	\$ 281.75	\$ 281.75
6	2 pcs	rear bumper side chrome moulding @\$106.95	broken	\$ 213.90	\$ 213.90
7	2 pcs	rear bumper side retainer @\$75.00	necessary	\$ 150.00	\$ 150.00
8	1 set	rear bumper clips	necessary	\$ 35.00	\$ 35.00
9	3 pcs	reverse sensor @\$299.00	not working	\$ 897.00	\$ 897.00
10	1 pc	r/h rear under cover	broken	\$ 364.55	\$ 364.55
11	1 pc	rear end panel	buckled	\$ 1,529.50	\$ 1,529.50
12	1 pc	rear end panel top garnish	broken	\$ 143.75	\$ 143.75
13	1 pc	spare tyre panel	damaged	\$ 586.50	\$ 586.50
14	1 pc	spare tyre r/h side panel	buckled	\$ 455.00	\$ 455.00
15	1 pc	rear wire harness	damaged	\$ 879.00	\$ 879.00
16	1 pc	bootlid	buckled	\$ 2,323.00	\$ 2,323.00
17	1 pc	bootlid inner lock	jammed	\$ 345.00	\$ 345.00
18	1 pc	bootlid chrome garnish	broken	\$ 143.75	\$ 143.75
19	1 pc	bootlid logo emblem	necessary	\$ 59.80	\$ 59.80
20	1 pc	bootlid "c180" emblem	necessary	\$ 89.70	\$ 89.70
21	1 pc	bootlid "cc" emblem	necessary	\$ 63.25	\$ 63.25
22	1 pc	bootlid inner trim	deformed	\$ 253.00	\$ 253.00
23	1 set	bootlid inner trim clips	necessary	\$ 35.00	\$ 35.00
24	1 pc	bootlid inner handle	deformed	\$ 224.25	\$ 224.25
25	1 pc	bootlid lock actuator w/ insulation cover	damaged	\$ 483.00	\$ 483.00
26	2 pcs	bootlid hinge @\$235.00	bent	\$ 470.00	\$ 470.00
27	2 pcs	bootlid hinge cowling @\$64.00	deformed	\$ 128.00	\$ 128.00
28	2 pcs	bootlid side drip cowling @\$76.00	deformed	\$ 152.00	\$ 152.00
29	1 pc	bootlid weatherstrip	deformed	\$ 287.50	\$ 287.50
30	1 pc	l/h taillamp	broken	\$ 805.00	\$ 805.00
31	1 pc	r/h taillamp	broken	\$ 805.00	\$ 805.00
32	1 pc	r/h taillamp inner panel	buckled	\$ 253.00	\$ 253.00
33	1 pc	r/h rear fender	buckled	\$ 2,415.00	\$ 2,415.00
34	1 pc	r/h rear fender inner trim	deformed	\$ 293.25	\$ 293.25
35	1 pc	r/h rear fender air vent	broken	\$ 29.90	\$ 29.90
36	1 pc	r/h rear door	damaged	\$ 2,357.50	repair
37	1 pc	front bumper	broken	\$ 1,702.00	\$ 1,702.00
38	1 pc	front bumper sponge	broken	\$ 178.25	\$ 178.25
39	1 pc	front bumper reinforcement	buckled	\$ 460.00	\$ 460.00
40	2 pcs	front bumper side retainer @\$79.00	necessary	\$ 158.00	\$ 158.00
		Less 10%		\$ 22,959.60	\$ 20,602.10
				\$ 22,959.60	\$ 18,541.89
Sub - Total				\$ 22,959.60	\$ 18,541.89



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/5722/0072/TP/09.19
Vehicle Number : **SMK 72E**

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 22,959.60	\$ 18,541.89
		LIST ITEMS:-			
41	1 pc	front bumper r/h tow hook cover	deformed	\$ 57.50	\$ 57.50
42	1 pc	front bumper lower grille	broken	\$ 138.00	\$ 138.00
43	2 pcs	front parking sensor @\$299.00	damaged	\$ 598.00	\$ 598.00
44	1 pc	front logo emblem w/ base	broken	\$ 166.75	\$ 166.75
45	1 set	front grille - complete	broken	\$ 978.00	\$ 978.00
46	1 pc	bonnet	buckled	\$ 2,277.00	\$ 2,277.00
47	1 pc	l/h headlamp	broken	\$ 3,507.50	\$ 3,507.50
48	1 pc	r/h headlamp	broken	\$ 3,507.50	\$ 3,507.50
49	1 pc	r/h front fender	buckled	\$ 920.00	\$ 920.00
50	1 pc	r/h front door	damaged	\$ 1,909.00	repair
51	1 pc	front support panel	buckled	\$ 782.00	\$ 782.00
52	1 pc	driver's seat belt	activated	\$ 965.20	\$ 965.20
53	1 pc	driver's seat belt buckle	activated	\$ 321.10	\$ 321.10
54	1 pc	l/h rear passenger's seat belt	activated	\$ 965.20	\$ 965.20
55	1 pc	r/h rear passenger's seat belt	activated	\$ 965.20	\$ 965.20
56	2 pcs	rear passenger's seat belt buckle @\$321.10	activated	\$ 642.20	\$ 642.20
		Less 10%		\$ 18,700.15	\$ 16,791.15
				\$ 18,700.15	\$ 15,112.04
		SPECIAL NETT ITEMS:-			
57	1 pc	rear no. plate	broken	\$ 60.00	\$ 50.00
58	1 pc	rear no. plate frame	broken	\$ 35.00	\$ 35.00
59	1 pc	front no. plate	broken	\$ 60.00	\$ 50.00
60	1 pc	front no. plate frame	broken	\$ 35.00	\$ 35.00
				\$ 190.00	\$ 170.00
			Sub - Total	\$ 41,849.75	\$ 33,823.93