

AIR DETAILS

erence

Source: MRM-SG Version: 1.0 (Last Synchronised: 18 May 2020)

nts: 143 NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

about: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP3644X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR RH <i>repair bt</i>	10.00	0.00	*930.60 FN
2	1		*REAR DOOR PROTECTOR RH <i>rec</i>	10.00	0.00	*291.80 FN
3	3		*REAR DOOR BLACK TAPE RH <i>rec</i>	10.00	0.00	*169.50 FN
4	1		*REAR DOOR HINGE LOWER RH <i>Xsuc</i>	10.00	0.00	*75.10 FN <i>X</i>
5	1		*FRONT DOOR RH <i>bt</i>	10.00	0.00	*980.60 FN
6	1		*FRONT DOOR PROTECTOR RH <i>ca</i>	10.00	0.00	*291.80 FN
7	3		*FRONT DOOR BLACK TAPE RH <i>ca</i>	10.00	0.00	*169.50 FN
8	1		*FRONT DOOR OUTER HANDLE RH <i>repair</i>	10.00	0.00	*297.30 FN <i>XR</i>
9	1		*FRONT DOOR LOCK <i>jam</i>	10.00	0.00	*431.10 FN
10	1		*FRONT DOOR CATCH <i>Xsuc</i>	10.00	0.00	*36.20 FN <i>X</i>
11	1		*FRONT DOOR REGULATOR C/W MOTOR <i>? bt</i>	10.00	0.00	*664.80 FN
12	10		*FRONT DOOR RIVET <i>ca</i>	10.00	0.00	*45.00 FN
13	1		*FRONT DOOR RUBBER RH <i>ca</i>	10.00	0.00	*185.30 FN
14	1		*FRONT DOOR LOWER RUBBER RH <i>? cut</i>	10.00	0.00	*54.20 FN
15	1		*FRONT DOOR INNER TRIM RH <i>? ca</i>	10.00	0.00	*597.40 FN
16	1		*ROCKER PANEL RH <i>bt</i>	10.00	0.00	*1,284.40 FN
17	1		*CENTRE PILLAR RH -REPAIR	10.00	0.00	-

F=Franchise part. N=NetItemDisc.

Sub Total (S\$)	6096.00	6,504.60
- Nett Item Discount on N Items (S\$)	102	650.46
Total Parts (S\$)	5486.40	5,854.14

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimate Report

ates on Miscellaneous Items

no new miscellaneous items selected.

estimates on Labour

Lab. Type	Amount
Particulars	
Labour Items	
1 TO REPAIR CENTRE PILLAR RH, FRONT DOOR PILLAR RH, REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS	New 500 840.00
2 TO SPRAY AFFECTED AREAS	New 600 850.00
3 TO REMOVE & REFIX DOOR MECHANISM CHECK & TEST POWER WINDOW & CENTRE LOCKING SYSTEM	New 60 80.00
4 TO REMOVE & REFIX DRIVER SIDE SAFETY BELT, CUSHION, CARPET AND OTHER ATTACHMENT PARTS	X New 800X 160.00 (photo)
5 TO RUST PROOF AFFECTED AREAS	New 60 100.00
	1220
Gross Labour Cost (S\$)	2,030.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rahul
Hp 9000068

5 days

4/5

20/05/2020 @ 0930

Reby after repair

5486.40

1220.00

6706.40

20%

5365.12

4/5 - 5350