

Estimate Report



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: EQ Insurance Company Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	15/05/2020
Vehicle Reg. No.:	SLP3644X	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOH KIA KIN		
Make/Model:	NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)	Vehicle Reg. Date:	31/05/2017
Vehicle Colour:	SILVER	Chassis No:	MNTBBAB17Z0027493
Engine No:	HR16990746B		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	30.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	5,854.14
Miscellaneous Items	0.00
Labour	2,030.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,884.14
+ GST 7.00% (S\$)	551.89
Nett Amount (S\$)	8,436.03

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimate Report

DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 May 2020)

Parts: 143 NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP3644X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR RH <i>repair bt</i>	10.00	0.00	*930.60 FN
2	1		*REAR DOOR PROTECTOR RH <i>rec</i>	10.00	0.00	*291.80 FN
3	3		*REAR DOOR BLACK TAPE RH <i>rec</i>	10.00	0.00	*169.50 FN
4	1		*REAR DOOR HINGE LOWER RH <i>X</i>	10.00	0.00	*75.10 FN
5	1		*FRONT DOOR RH <i>bt</i>	10.00	0.00	*980.60 FN
6	1		*FRONT DOOR PROTECTOR RH <i>cm</i>	10.00	0.00	*291.80 FN
7	3		*FRONT DOOR BLACK TAPE RH <i>rec</i>	10.00	0.00	*169.50 FN
8	1		*FRONT DOOR OUTER HANDLE RH <i>repair</i>	10.00	0.00	*297.30 FN
9	1		*FRONT DOOR LOCK <i>jam</i>	10.00	0.00	*431.10 FN
10	1		*FRONT DOOR CATCH <i>?</i>	10.00	0.00	*36.20 FN
11	1		*FRONT DOOR REGULATOR C/W MOTOR <i>?</i>	10.00	0.00	*664.80 FN
12	10		*FRONT DOOR RIVET <i>rec</i>	10.00	0.00	*45.00 FN
13	1		*FRONT DOOR RUBBER RH <i>rec</i>	10.00	0.00	*185.30 FN
14	1		*FRONT DOOR LOWER RUBBER RH <i>?</i>	10.00	0.00	*54.20 FN
15	1		*FRONT DOOR INNER TRIM RH <i>?</i>	10.00	0.00	*597.40 FN
16	1		*ROCKER PANEL RH <i>bt</i>	10.00	0.00	*1,284.40 FN
17	1		*CENTRE PILLAR RH -REPAIR	10.00	0.00	-

F=Franchise part. N=NetItemDisc.

Sub Total (\$\$)	6,504.60
- Nett Item Discount on N Items (\$\$)	650.46
Total Parts (\$\$)	5,854.14

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimate Report

on Miscellaneous Items
new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR CENTRE PILLAR RH, FRONT DOOR PILLAR RH, REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS	New	500 840.00
2	TO SPRAY AFFECTED AREAS	New	600 850.00
3	TO REMOVE & REFIX DOOR MECHANISM CHECK & TEST POWER WINDOW & CENTRE LOCKING SYSTEM	New	60 80.00
4	TO REMOVE & REFIX DRIVER SIDE SAFETY BELT, CUSHION, CARPET AND OTHER ATTACHMENT PARTS	New	80 160.00 (photo)
5	TO RUST PROOF AFFECTED AREAS	New	60 100.00
Gross Labour Cost (S\$)			2,030.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rahul
Hp 90000068
5 days
H/S
20/05/2020 @ 0930
Reby after repair