

ASS. REC. BY:

REF:

TU / 2000 5822 / Kea392

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL S 7539 A

Yr Regn:

10, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius A

c.c

1798

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

236031

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD KB 3FU X 03571024

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

16/5/20

D.O.I.

19/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/5 @ 786.95 Cash/m

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

S - RS, SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

CLOSE: 13/8/2020

Indira
Kenneth



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLS 7539 A

Not Authorized
Resurvey After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Parts	(a) Cost / List Price Items	\$	1,120.10
	Plus/Less 25%	\$	280.03
	Total of Cost / List	\$	840.08
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	970.00
Total		\$	1,810.08

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 19/5/20 at 10.30am

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Le Date: 19/5/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLS 7539 A**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FUX03571024**

Submit By : **Carmen Lim**
Year Manufacture : **2017 Oct**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper <i>R Red</i>	1	\$497.50		X
2	Rear bumper clip <i>nn</i>	10	\$40.00		X
3	Rear bumper lower garnish centre <i>nn</i>	1	\$582.60		✓
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

