

Indra Kenneth



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLS 7539 A

Parts (a) Cost / List Price Items	\$	1,120.10
Plus/Less 25%	\$	280.03
Total of Cost / List	\$	840.08
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items		
Total Parts Cost		
Labour	\$	970.00
Total	\$	1,810.08

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor

Company

Survey conducted on

Kenneth

LKK

19/5/20

at

10.30am

Remarks By Surveyor

(a) The repair of this vehicle is ~~not~~ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$

(e) Signature of surveyor

Lc

Date:

19/5/20

**ESTEEM
PERFORMANCE****ESTEEM PERFORMANCE PTE LTD**Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg**Spare Parts**Vehicle No. : **SLS 7539 A**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FUX03571024**Submit By : **Carmen Lim**
Year Manufacture : **2017 Oct**
Engine No. :**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper <i>R. Part</i>	1	\$497.50		X
2	Rear bumper clip <i>nm</i>	10	\$40.00		X
3	Rear bumper lower garnish centre <i>nm</i>	1	\$582.60		✓
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempdf.com.sg

Vehicle No. : **SLS 7539 A**
Make & Model : **TOYOTA PRIUS**

Year of Manufacture : 2017 Oct

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.