



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

18/5/2020

Vehicle:

SMF9608C

Make / Model:

KIA CERATO FORTE

Chassis No:

KNAF3416MK5018125

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / <i>DD</i>	1	\$ 798.00	\$ 798.00
2	REAR BUMPER REINFORCEMENT <i>?</i> / <i>DR</i>	1	\$ 380.00	\$ 380.00
3	REAR BUMPER SIDE RETAINER LH / <i>DR</i>	1	\$ 35.00	\$ 35.00
4	REAR BUMPER SIDE RETAINER RH / <i>DR</i>	1	\$ 35.00	\$ 35.00
5	REAR BUMPER LOWER LIP SPOILER / <i>CMT</i>	1	\$ 434.00	\$ 434.00
6	REAR BUMPER LAMP LH X <i>NM</i>	1	\$ 155.00	\$ 155.00
7	REAR BUMPER LAMP OUTER GARNISH LH <i>?</i> / <i>DR</i>	1	\$ 107.00	\$ 107.00
8	REAR BUMPER LAMP RH X <i>NM</i>	1	\$ 155.00	\$ 155.00
9	REAR BUMPER LAMP OUTER GARNISH RH X <i>NM</i>	1	\$ 107.00	\$ 107.00
10	REAR BOOTLID X <i>R</i>	1	\$ 954.00	\$ 954.00
11	REAR BOOTLID LOCK X <i>NM</i>	1	\$ 212.00	\$ 212.00
12	REAR BOOTLID LOCK CATCH X <i>NM</i>	1	\$ 60.00	\$ 60.00
13	REAR BOOTLID EMBLEM LOGO / <i>IPC</i>	1	\$ 57.00	\$ 57.00
14	REAR BOOTLID EMBLEM CERATO / <i>IPC</i>	1	\$ 49.00	\$ 49.00
15	REAR BOOTLID INNER TRIM BOARD X <i>NM</i>	1	\$ 95.00	\$ 95.00
16	REAR BOOTLID LAMP LH X <i>NM</i>	1	\$ 405.00	\$ 405.00
17	REAR BOOTLID LAMP RH X <i>NM</i>	1	\$ 405.00	\$ 405.00
18	REAR BOOTLID CENTER LAMP X <i>NM</i>	1	\$ 410.00	\$ 410.00
19	REAR BOOT WEATHER STRIPE / <i>TN</i>	1	\$ 102.00	\$ 102.00
20	REAR TAILLAMP LH X <i>NM</i>	1	\$ 609.00	\$ 609.00
21	REAR TAILLAMP RH X <i>NM</i>	1	\$ 609.00	\$ 609.00
22	REAR END PANEL X <i>R</i>	1	\$ 665.00	\$ 665.00
23	REAR END PANEL TOP GARNISH <i>?</i> / <i>CRM</i>	1	\$ 160.00	\$ 160.00
24	REAR KEYLESS SENSOR X <i>NM</i>	1	\$ 175.00	\$ 175.00
25	REAR SPARE TYRE TOP COVER X <i>NM</i>	1	\$ 260.00	\$ 260.00
				\$ 6,998.00
			Less 10%	\$ 699.80
			Total	\$ 6,298.20
S/Nett items:				
1	REAR REVERSE SENSOR / <i>SLY</i>	1 SET	\$ 250.00	\$ 250.00
2	REAR REVERSE CAMERA X <i>NM</i>	1 SET	\$ 300.00	\$ 300.00
3	REAR NUMBER PLATE WITH CASING X <i>NM</i>	1	\$ 60.00	\$ 60.00
4	REAR BUMPER CLIP / <i>IPC</i>	1 SET	\$ 80.00	\$ 80.00
5	REAR END PANEL GARNISH CLIP / <i>IPC</i>	1 SET	\$ 30.00	\$ 30.00
6	FLOOR PANEL SEALANT X <i>NM</i>	1	\$ 50.00	\$ 50.00
7	END PANEL SEALANT X <i>NM</i>	1	\$ 50.00	\$ 50.00
8	MISCELLANEOUS X <i>NM</i>	1	\$ 200.00	\$ 200.00
				\$ 1,020.00

270

37
10

SMF9608C

Labour to:				
1	TO CHECK ELECTRICAL WIRING <i>LKK</i>	1	\$ 80.00	\$ 80.00 <i>70</i>
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00 <i>30</i>
3	REPAIR AND STRAIGHTEN EXHAUST PIPE	1	\$ 150.00	\$ 150.00 <i>X</i>
4	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 150.00	\$ 150.00 <i>X</i>
5	REMOVE AND TRANSFER ALL REAR BOOTLID FITTING	1	\$ 150.00	\$ 150.00 <i>50</i>
6	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 120.00	\$ 120.00 <i>X</i>
7	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00 <i>X</i>
8	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00 <i>30</i>
9	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00 <i>600</i>
10	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00 <i>600</i>
				\$ 3,150.00
			Parts Replacement Amount	\$ 7,318.20
			Total Amount for Labour	\$ 3,150.00
			Total Amount	\$ 10,468.20

Steve (LKK) *ML AL*

4 dgs

19/5/77, 11.30am

L/S

My AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: