



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934
HP: 98888885

Estimation

Date: 18/5/2020

Vehicle: SMF9608C

Make / Model: KIA CERATO FORTE

Chassis No: KNAF3416MK5018125

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / DD	1	\$ 798.00	\$ 798.00
2	REAR BUMPER REINFORCEMENT ? / BR	1	\$ 380.00	\$ 380.00
3	REAR BUMPER SIDE RETAINER LH / BR	1	\$ 35.00	\$ 35.00
4	REAR BUMPER SIDE RETAINER RH / BR	1	\$ 35.00	\$ 35.00
5	REAR BUMPER LOWER LIP SPOILER / CM	1	\$ 434.00	\$ 434.00
6	REAR BUMPER LAMP LH X NM	1	\$ 155.00	\$ 155.00
7	REAR BUMPER LAMP OUTER GARNISH LH ? / BR	1	\$ 107.00	\$ 107.00
8	REAR BUMPER LAMP RH / BR	1	\$ 155.00	\$ 155.00
9	REAR BUMPER LAMP OUTER GARNISH RH X NM	1	\$ 107.00	\$ 107.00
10	REAR BOOTLID X R	1	\$ 954.00	\$ 954.00
11	REAR BOOTLID LOCK X NM	1	\$ 212.00	\$ 212.00
12	REAR BOOTLID LOCK CATCH X NM	1	\$ 60.00	\$ 60.00
13	REAR BOOTLID EMBLEM LOGO / PC	1	\$ 57.00	\$ 57.00
14	REAR BOOTLID EMBLEM CERATO / PC	1	\$ 49.00	\$ 49.00
15	REAR BOOTLID INNER TRIM BOARD X NM	1	\$ 95.00	\$ 95.00
16	REAR BOOTLID LAMP LH X NM	1	\$ 405.00	\$ 405.00
17	REAR BOOTLID LAMP RH X NM	1	\$ 405.00	\$ 405.00
18	REAR BOOTLID CENTER LAMP X NM	1	\$ 410.00	\$ 410.00
19	REAR BOOT WEATHER STRIPE / TN	1	\$ 102.00	\$ 102.00
20	REAR TAILLAMP LH X NM	1	\$ 609.00	\$ 609.00
21	REAR TAILLAMP RH X NM	1	\$ 609.00	\$ 609.00
22	REAR END PANEL / DD	1	\$ 665.00	\$ 665.00
23	REAR END PANEL TOP GARNISH ? / CRH	1	\$ 160.00	\$ 160.00
24	REAR KEYLESS SENSOR X NM	1	\$ 175.00	\$ 175.00
25	REAR SPARE TYRE TOP COVER X NM	1	\$ 260.00	\$ 260.00
				\$ 6,998.00
			Less 10%	\$ 699.80
			Total	\$ 6,298.20
S/Nett items:				
1	REAR REVERSE SENSOR / SL	1 SET	\$ 250.00	\$ 250.00
2	REAR REVERSE CAMERA X NM	1 SET	\$ 300.00	\$ 300.00
3	REAR NUMBER PLATE WITH CASING X NM	1	\$ 60.00	\$ 60.00
4	REAR BUMPER CLIP / PC	1 SET	\$ 80.00	\$ 80.00
5	REAR END PANEL GARNISH CLIP / PC	1 SET	\$ 30.00	\$ 30.00
6	FLOOR PANEL SEALANT X NM	1	\$ 50.00	\$ 50.00
7	END PANEL SEALANT X NM	1	\$ 50.00	\$ 50.00
8	MISCELLANEOUS X NM	1	\$ 200.00	\$ 200.00
				\$ 1,020.00

688 /

347 /

598 /

2713

-10%

2441.70

290 /

30 /

10 /

240

SMF9608C

Labour to:				
1	TO CHECK ELECTRICAL WIRING <i>KKK</i>	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	REPAIR AND STRAIGHTEN EXHUAUST PIPE	1	\$ 150.00	\$ 150.00
4	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 150.00	\$ 150.00
5	REMOVE AND TRANSFER ALL REAR BOOTLID FITTING	1	\$ 150.00	\$ 150.00
6	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 120.00	\$ 120.00
7	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
8	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
9	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
10	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
				\$ 3,150.00
			Parts Replacement Amount	\$ 7,318.20
			Total Amount for Labour	\$ 3,150.00
			Total Amount	\$ 10,468.20

70
 30
 X
 X
 50
 X
 X
 30
 600
 700
 1440

Steve (LKK) *ML AL*
 4 dgs
 19/5/79, 11.30am
 L/S

My AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2441-79

M-249

L-1440

4121-79

L/S - 3297-36

= 3300