

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
Tel: +65 6255 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SME4595T
Make & Model : Renault, Grand Scenic IV 1.5 dCi AT
EU6,VF1RFA00461280826
Year of Manufacture : 2018

Estimation No. : E20050003
Date : 18/05/2020

No.	Description	Qty	U/P	Amt
<u>Section: Remark</u>				
1	TP CLAIM AGAINST CHINA TAIPING INSURANCE SINGAPORE PTE LTD CLAIM NO: SNM20D201943 DOA: 17.05.2020 OIC: ADELINE CHNG SURVEYOR: KENNETH KONG (LKK)	1.00	0.00	0.00
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

*NOT Authorised
Returning By Paint
4-5 days
L1 Imp @ 7700/-*

<u>Section: Parts</u>				
2	REAR BUMPER	CM 1.00	1,152.96	1,152.96 ✓
3	REAR BUMPER LOWER MOULDING	Rel 1.00	696.24	696.24 ✓
4	REAR BUMPER CENTRE BRACKET	R 1.00	357.84	357.84 ✓
5	REAR BUMPER SUPPORT BRACKET LH	R 1.00	113.88	113.88 X
6	REAR BUMPER BRACKET LH	R 1.00	288.96	288.96 X
7	REAR BUMPER REINFORCEMENT	R 1.00	685.68	685.68 ✓
8	REAR WIPER ARM	Sn 1.00	160.92	160.92 X
9	REAR WIPER BLADE	Sn 1.00	39.00	39.00 X
10	TAILGATE LAMP LH	CM 1.00	548.88	548.88 ✓
11	TAILLAMP LH	CM 1.00	548.88	548.88 ✓
12	REAR LOGO 'DIAMOND'	M 1.00	165.72	165.72 ✓
13	REAR EMBLEM 'RENAULT'	M 1.00	130.56	130.56 ✓
14	REAR EMBLEM 'SCENIC'	M 1.00	151.44	151.44 ✓
15	TAILGATE OUTER PANEL	R 1.00	755.40	755.40 X
16	TAILGATE OUTER PANEL CHROME	Sn 1.00	473.16	473.16 X
17	TAILGATE TOP SPOILER	Rel 1.00	383.88	383.88 ✓
18	REAR WINDSCREEN GLASS	Shattered 1.00	954.24	954.24 ✓
19	TAILGATE ASSY 1929.90	CM 1.00	2,433.84	2,433.84 ✓
20	TAILGATE HINGE LH	R 1.00	508.80	508.80 X
21	TAILGATE HINGE RH	R 1.00	508.80	508.80 X

108

Continue on next page...

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
Tel: +65 6255 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

Vehicle No : SME4595T
Make & Model : Renault, Grand Scenic IV 1.5 dCi AT
EU6,VF1RFA00461280826
Year of Manufacture : 2018

ESTIMATION REPORT

Estimation No. : E20050003
Date : 18/05/2020

No.	Description	Qty	U/P	Amt
				Amt S\$
				11,059.08
				Discount (10.00%) S\$ 999.99
				Subtotal S\$ 9,953.17

Section: Special nett

22	REAR PARKING SENSOR	MIT 2.00	255.36	510.72 ✓
23	REVERSE CAMERA	212 1.00	707.88	707.88 ✓
24	REVERSE CAMERA TRIM	Sm 1.00	157.80	157.80 ✗
25	WINDSCREEN SEALANT	2.00	25.00	50.00 4012
26	TAILGATE CLIPS	6.00	5.00	30.00 ✓

Amt S\$ 1,456.40
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,456.40

Section: Labour

27	LABOUR FOR SPRAY PAINT TAILGATE, REAR BUMPER, REAR SPOILER, REAR END PANEL & REAR FENDER LH	1.00	1,600.00	1,600.00 6001
28	LABOUR FOR WELDING & KNOCKING REAR END PANEL AND ALL AFFECTED AREAS	1.00	1,000.00	1,000.00 7501
29	TO CHECK WIRING & SYSTEM FUNCTION	1.00	120.00	120.00 201
30	LABOUR FOR INSTALL NEW REAR WINDSCREEN GLASS	1.00	200.00	200.00 1201
31	LABOUR FOR INSTALL REVERSE SENSOR AND REAR IN CAR CAMERA	1.00	120.00	120.00 901
32	TO APPLY RUST PROOFING ON AFFECTED AREAS	411 1.00	100.00	100.00 ✗
33	TO CHECK TAILGATE WATER SEEPAGE	1.00	80.00	80.00 201
34	LABOUR FOR REMOVE & INSTALL ALL PARTS AS ABOVE	1.00	300.00	300.00 601
35	TO INSTALL REAR WINDSCREEN SOLAR FILM	1.00	200.00	200.00 1001

Amt S\$ 3,720.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,720.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Remark Subtotal S\$ 0.00
Parts Subtotal S\$ 9,953.17
Special nett Subtotal S\$ 1,456.40
Labour Subtotal S\$ 3,720.00
Total S\$ 15,129.57