

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

Not Authorized

11 May 8

Remedy After Paint

20 MAY 2020

6 days

LKK Kenneth

DATE: 19-May-20

INSURANCE: INDIA

MODEL: Mercedes-Benz E200

VEHICLE NO.: SMK 3131 Z

DESCRIPTION	QTY	UNIT PRICE	NETT PRICE
FRONT BUMPER	1	Bu	\$1,760.00
FRONT BUMPER SPONGE	1		\$149.00
RH FRONT BUMPER INNER PART	1		\$142.00
FRONT BUMPER REINFROCEMENT	1		\$600.00
FRONT BUMPER RETAINER	2	\$90.00	\$180.00
FRONT BUMPER SENSOR	2	\$306.00	\$612.00
RH FRONT BUMPER FOG LAMP COVER	1		\$63.00
FRONT BUMPER LOWER CHROME - CENTRE	1		\$330.00
FRONT BUMPER LOWER CHROME - SIDE	2	\$250.00	\$500.00
FRONT GRILLE	1		\$945.00
FRONT GRILLE EMBLEM	1		\$143.00
HEAD LAMPS	2	\$5,428.00	\$10,856.00
RH FRONT FENDER	1		\$1,119.00
RH FRONT FENDER UNDER-SHIELD	1		\$218.00
FRONT FENDER EDITION E EMBLEM	2	\$119.00	\$238.00
BONNET	1		\$2,600.00
FRONT WINDSCREEN GLASS	1	Pinned	\$1,965.00
<b>SUB TOTAL</b>			\$22,420.00
<b>LESS 10%</b>			\$2,242.00
<b>DISCOUNTED TOTAL</b>			\$20,178.00
FRONT WINDSCREEN SEALANT	1	S.NETT	\$40.00
FRONT WINDSCREEN IU BRACKET	1	S.NETT	\$25.00
FRONT WINDSCREEN SOLAR FLIM	1	(Bill)	\$600.00
<b>SUB TOTAL</b>			\$625.00
<b>Labour Charge</b>			
Panel Beating	1	\$900.00	\$900.00
Spray Painting Charge	1	\$1,500.00	\$1,500.00
Anti-rust	1	\$150.00	\$150.00
Replace front Windscreen Glass	1	\$180.00	\$180.00
Treatment			\$980.00
<b>TOTAL LABOUR</b>			\$3,710.00
<b>ESTIMATE TOTAL</b>			\$24,513.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.