

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joel Goh

Date: 21 May 2020

## **Preliminary Advice**

Insured Vehicle No	: SMD1856R		
TP Vehicle No	: SHA7871G	Accident Date	: 19/05/2020
Make	: HYUNDAI I40	Assignment Date	: 20/05/2020
Date of Inspection	: 20/05/2020	Est. Duration of Repair	: 3.00
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and n/s parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,050.16
Revised Amount	:S\$	3,168.08
Check Items (Estimated)	:S\$	17,92
Total	:S\$	3,186.00

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Surevy on "WP"