Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI20005834/FTF3E2

D4FDEU500060

Date: 27/05/2020

REFERENCE

Handling Insurer: EQ Insurance Company Ltd Policy No: DMPPHQ19-005429

Claimant Vehicle SHA7871G Insured Vehicle No: SMD1856R

No:

ΤP Date of Loss: 19/05/2020 Nature of Claim: Claim No: DM20HO00827

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA7871G

HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR Make & Model: Engine No:

Reg. Date: 30/06/2015 (Man. Year: 2015) Chassis No: KMHLB41UMGU075111

Colour: Blue Odometer: 800860 km

Engine Capacity: 1685 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: Nο

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 205/60 R16 Rear Tyre Size: Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: Rear Right Side: West Lake 6 mm West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,600.16	1,930.15	2,670.01	58.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,130.00	320.00	22.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,050.16	3,060.15	2,990.01	49.42
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	6,050.16	2,450.00	3,600.16	59.51
+ GST 7.00/7.00% (S\$)	423.51	171.50	252.01	59.51
Nett Amount (S\$)	6,473.67	2,621.50	3,852.17	59.51

INSPECTION

ComfortDelGro Engineering Pte Ltd Date of Assignment: 20/05/2020 Present Location:

(Loyang)

Date Inspected: 20/05/2020 Inspected At: ComfortDelGro Engineering Pte Ltd

> (Loyang) 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: PARASURAM SHANMUGAM Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2020)	
Parts: Labour:	143 Repairer's	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0) (Price-denominated Standard List)	
Print Code:	: (Unsubmitted, no print-code for SHA7871G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values n	ot in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET ASSY	Repair	2,265.90 FL	*-FL
2	1		*HEAD LAMP LH	Scratched	1,388.00 FL	*1,388.00 FL
3	1		*FRONT BUMPER ASSYH	Cracked / Dented	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SIDE LH	Not Necessary	14.30 FL	*-FL
5	1		*FRONT BUMPER TOP BRACKET LH	Not Necessary	22.40 FL	*-FL
6	1		*FRONT SUPPORT PANEL	Not Necessary	907.40 FL	*-FL
7	1		*FRONT ADVERTISEMENT	Necessary	100.00 FL	*100.00 FS
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,750.20	2,540.20
	- List Item Discount on L Items 20.00/25.00% (S\$)			1,150.04	610.05	
	Total Parts (S\$)			4,600.16	1,930.15	

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	720.00	700.00
2	SPRAY PAINTING	New	500.00	400.00
3	CHECH WIRING	New	50.00	30.00
4	REMOVR/REFIX AC CONDENSER & CHARGE GAS	New	120.00	0.00
5	TUFF KOTE	New	60.00	0.00
	Gross L	_abour Cost (S\$)	1,450.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >