

HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722

Hp : 9183 3008

Fax : 6873 2017

Vehicle No : SKG2686R
Vehicle Model : Honda Odyssey

*Not Authorized
61 Smp 83200h
Presumy After Paint
5 days*

Estimate Repair Cost

No.	Qty	Parts List Items
1	1	Rear bumper
2	2	Rear bumper brackets
3	1 set	Rear bumper clips
4	2	Rear bumper reflectors
5	2	Rear bumper retainers
6	1	Rear tailgate <i>1100</i>
7	1	Rear tailgate lock
8	1	Rear tailgate centre logo
9	1	Rear tailgate outer chrome top moulding
10	1	Rear tailgate outer chrome bottom moulding
11	2	Rear tailgate hinges
12	2	Rear tailgate dampers
13	1	Rear tailgate inner trim board
14	1 set	Rear tailgate inner trim clips
15	2	Rear tailgate inner side garnishes
16	2	Tail lamps (outer & inner)
17	1	Rear windscreen moulding
18	1	Rear wiper arm
19	1	Rear end panel
20	1	Rear end panel top garnish
21	1	Rear spare tyre compartment
22	1	Rear spare tyre top board
23	1	Rear exhaust silencer
24	1	Rear exhaust silencer mounting

<i>Bu</i>	\$	782.60	✓
	\$	<i>R</i> 131.20	X
<i>new</i>	\$	40.00	✓
	\$	<i>Sn</i> 166.80	X
	\$	<i>Sn</i> 84.90	X
<i>By</i>	\$	1,259.80	✓
	\$	<i>R</i> 218.10	✓
	\$	<i>new</i> 30.90	✓
	\$	<i>Sn</i> 283.10	X
<i>warp/mg</i>	\$	<i>By</i> 218.50	✓
	\$	<i>R</i> 184.00	X
<i>mg/cm</i>	\$	<i>Sn</i> 387.40	X
	\$	<i>Sn</i> 342.70	✓
	\$	<i>new</i> 60.00	✓
	\$	<i>Sn</i> 850.30	X
	\$	<i>Sn</i> 1,972.10	X
	\$	<i>new</i> 120.00	✓
	\$	<i>Sn</i> 80.10	X
<i>nd</i>	\$	<i>R</i> 542.10	<i>#1205w</i>
	\$	<i>Sn</i> 121.90	X
	\$	<i>R</i> 721.50	X
	\$	<i>Sn</i> 345.90	X
	\$	<i>R</i> 764.30	X
	\$	<i>Sn</i> 84.80	X
	\$	<u>9,793.00</u>	

Parts Special Nett Items

25	1	Rear number plate
26	<i>1x</i>	Reverse sensor

	\$	<i>Sn</i> 60.00	X
<i>shorted 2005w</i>	\$	600.00	<i>Lx</i>
Total	\$	<u>660.00</u>	

Total Parts \$ 10,453.00

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 2,000.00	500/
2	To putty and respray painting on affected areas.	\$ 1,200.00	600/
3	To remove, replace rear tailgate fittings to facilitate repair.	\$ 250.00	60/
4	To remove, replace rear windscreen glass.	\$ 200.00	120/
5	To remove, replace reverse sensor.	\$ 200.00	60/
6	To remove, replace rear exhaust silencer.	\$ 100.00	X
7	To check wiring and lightings.	\$ 80.00	20/

Total Labour \$ 4,030.00

Total Parts and Labour \$ 14,483.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: