



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005085  
INV Date 20/07/2020  
Reference CC4/FCI20005843/Kba3s2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. GBB 8631S  
Insured Veh. SHA 8506E  
Claim No. D20002161MFSH  
Policy No. D-20094921MFSH  
Accident Date 13/05/2020  
Inspection Date 21/05/2020

Description	Total
Third Party Express Settlement	162.00
<b>Subtotal</b>	<b>162.00</b>
<b>GST (7%)</b>	<b>11.34</b>
<b>Grand Total</b>	<b>173.34</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20005843/Kba3s2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 20-07-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 8506E	<b>Veh. Inspected</b>	GBB 8631S
<b>Policy No.</b>	D-20094921MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20002161MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ERIC WOO	<b>Assign Date</b>	20/05/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	CITROEN NEMO (M)	<b>c.c</b>	1399
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
<b>Chassis No.</b>	VF7AABHSC94899862	<b>Colour</b>	BLACK
<b>Odometer</b>	185052	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/60 R15	HABILEAD	8 mm
<b>L/H Front Tyre</b>	195/60 R15	HABILEAD	8 mm
<b>R/H Rear Tyre</b>	195/60 R15	HABILEAD	8 mm
<b>L/H Rear Tyre</b>	195/60 R15	HABILEAD	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	13/05/2020	<b>Inspection Date</b>	21/05/2020
<b>Survey held at</b>	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 8631S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DENTED / CUT	480.00	480.00
1	FRONT FENDER - LH	TO REPAIR SEE LABOUR	395.00	-
	LESS 10% DISCOUNT		-87.50	-48.00
			787.50	432.00
	<b><u>LABOUR</u></b>			
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER - LH.		250.00	200.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		350.00	200.00
			600.00	400.00
	<b>GRAND TOTAL</b>		<b>1,387.50</b>	<b>832.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>650.00</b>

Report Ref No. CC4/FCI20005843/Kba3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 8631S

INSPECTION






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



CHASSIS NO. : VF7AABHSC94899962  
U.W. : 1180KG  
M.L.W. : 1700KG  
PASS. CAP : 1 DRIVER 1 OTHERS  
TYRE SIZE : F185/65R15  
R185/65R15 (S)