

(08/11/13) Wef

ASS. REC. BY: *Marcus*

REF:

CC4/ASM2005852/UK93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

Sub. Rep 17/12. net 3900

29/5/20 4/5 3000 confirmed with Tony



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

444 kharchna

not Authorised
Haha

2/5/20

2/s 3000/?
3 days

to be phd. Affair up in

Model: **MERCEDES BENZ C180 BLUEEFFICIENCY**

Veh No: **SKS4360D**

BACK

Qty	List Items	Amount S\$
1	REAR BUMPER 1315.00	del 70% 1875.8 ✓
1	* REAR BUMPER TOW COVER	11 119.2 X
2	REAR BUMPER SIDE BRACKET @ 215.20	11 430.4 X
2	REAR BUMPER LOWER BRACKET @ 318.60	11 637.2 X
1	REAR BUMPER CENTER OUTER MOULDING 176	rec 435 ✓
2	REAR BUMPER SIDE OUTER MOULDING @ 242	rec 484 ✓
2	REAR BUMPER LOWER SUPPORT @ 41	11 82 X
1	REAR BUMPER CENTER RETAINER	11 260.4 X
2	REAR BUMPER SIDE RETAINER @ 110.10	11 220.2 X
1	REAR BUMPER REINFORCEMENT 619	sent 859.6 ✓
2	REAR TAIL LAMP L R @ 1139.70 630.50	n/scre 2279.4 ✓
2	REAR TAIL LAMP LOWER BRACKET @ 211.30	11 422.6 X
1	REAR END PANEL	11 1027.2 X
1	REAR END PANEL TOP GARNISH	11 312.4 X
1	REAR FLOOR PANEL TOP BOARD	11 695.9 X
1	BOOT LID	11 2028.2 X
1	BOOT LID CHROME MOULDING	11 354.1 X
1	BOOT LID WEATHERSTRIP	11 332.8 X
1	* BOOT LID LOCK ASSY	11 250.1 X
1	BOOT LID LOCK COVER	11 76.3 X
1	REVERSE SENSOR @ 390	11 1560 200 S.N
Sub Total		14742.8
Less 10%		1474.28
		13268.52

Special Nett Items

Qty	List Items	Amount S\$
1 SET	REAR BUMPER CLIPS	rec 70 50
1	REAR BOOT LID JOINT SEALANT	11 90 X
1 SET	REAR BOOT LID INNER TRIM CLIPS	11 70 X
1	BOOT LID MERCEDES BENZ LOGO	11 78 X
1	BOOT LID EMBLEM "C180"	11 95 X
1	BOOT LID C&C LOGO	11 65 X
1	BOOT LID EMBLEM "KOMPRESSOR"	11 145 X
1 SET	REAR END PANEL TOP GARNISH CLIP	11 45 X
1	* REAR END PANEL JOINT SEALANT	11 90 X
Sub Total		748

1.2970.5
100
8-2673.45
S.N-250.00
1-870.00
3793.45
3034.



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

Model : MERCEDES BENZ C180 BLUEEFFICIENCY

Veh No: SKS4360D

Labour charges

CHECK ELECTRICAL WIRING	100	20
CHECK WHEEL ALIGNMENT	100	X
INSTALL REVERSE SENSORS	100	50
TUFFKOTE	200	X
RESPRAY PAINTING	1300	400
PANEL BEATING, REMOVE AND REPLACE ABOVE PARTS ETC	1400	400
Sub Total	3200	

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

17216.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: