

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 May 2020 Sendback Est	20 May 2020 15:48 S\$1,386.90	20 May 2020 18:02 Edit Adj Rpt	S\$1,005.50 Edit Estimates	S\$1,005.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: STRIDES TRANSPORTATION PTE LTD , Co. Reg. No.: 201607143W									
Main Claimant: STRIDES TRANSPORTATION PTE LTD , Co. Reg. No.: 201607143W									
Vehicle Reg. No.:	SMS2666L	Date of Loss:	19/05/2020 16:00 - :59 [3 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D201950/C02/THAMYL	Policy/Cover Note No.:	DMCVSN16275219033						
Vehicle Reg. No. (Insured):	SKF4243C	Policy No. (Claimant):	M0015437						
		Excess:	S\$0.00						
Repairer:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane, 739145 Woodlands - Tel: 3157 2626								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Pauline Tham]								
Claimant's Insurer:	Etiqa Insurance Pte Ltd (HQ) - Tel: 63360477								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 01/06/2020]								
Driver/Custodian (Insured):	LEE YI DA (/ Male) Email:								
		Vehicle Source:	Drive/Walk-in						
Adj Asg. Remarks:	OI HAVE NOT MAKE THE ACCIDENT REPORT. PLEASE CONDUCT PRS ON WITHOUT PREJUDICE BASIS.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPING (20/05/2020): Cancellation of Assignment: SMS2666L									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SMS2666L (SNM20D201950/C02/THAMYL)
[SKF4243C]
TP
STRIDES TRANSPORTATION PTE LTD
May 19 2020 4:00PM
[STRIDES TRANSPORTATION PTE LTD]
Auto Insure Pte Ltd (HQ)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports					1 per page	☒
No	Finalized On	Auto Insure Pte Ltd (HQ) (Woodlands)		Thumbnail	Print	
1	20/05/20 15:48	Repairer Estimates		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	22/05/20 14:18	Adjuster Immediate Advice		Load HTM		
Photos/Images					3 per page	☒
No	Finalized On	Auto Insure Pte Ltd (HQ) (Woodlands)		Thumbnail	Print	
1	20/05/20 15:45	Front View Right		Load JPG	☒	
2	20/05/20 15:45	Front View Left		Load JPG	☒	
3	20/05/20 15:45	Front View		Load JPG	☒	
4	20/05/20 15:45	FRONT NUMBER PLATE BRACKET		Load JPG	☒	
5	20/05/20 15:45	FRONT NUMBER PLATE		Load JPG	☒	
6	20/05/20 15:45	FRONT RADIATOR GRILLE		Load JPG	☒	
7	20/05/20 15:45	FRONT RADIATOR GRILLE		Load JPG	☒	
8	20/05/20 15:45	FRONT RADIATOR GRILLE		Load JPG	☒	
9	20/05/20 15:45	FRONT BUMPER		Load JPG	☒	
10	20/05/20 15:45	FRONT LOWER RADIATOR GRILLE		Load JPG	☒	
11	20/05/20 15:45	FRONT LOWER RADIATOR GRILLE		Load JPG	☒	
12	20/05/20 15:45	Odometer Reading		Load JPG	☒	
13	20/05/20 15:45	BADGE CHASSIS		Load JPG	☒	
14	20/05/20 15:45	TIRE BRAND & SIZE		Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	22/05/20 12:08	Odometer Reading		Load JPG	☒	
2	22/05/20 12:08	Chassis Number		Load JPG	☒	
3	22/05/20 12:08	General View		Load JPG	☒	
4	22/05/20 12:08	General View		Load JPG	☒	
5	22/05/20 12:08	General View		Load JPG	☒	
6	22/05/20 12:08	General View		Load JPG	☒	
7	22/05/20 12:08	General View		Load JPG	☒	
8	22/05/20 12:08	General View		Load JPG	☒	
9	22/05/20 12:08	General View		Load JPG	☒	
10	22/05/20 12:08	General View		Load JPG	☒	
11	22/05/20 12:08	General View		Load JPG	☒	
12	22/05/20 12:08	General View		Load JPG	☒	
13	22/05/20 12:08	General View		Load JPG	☒	
14	22/05/20 12:08	General View		Load JPG	☒	
15	22/05/20 12:08	General View		Load JPG	☒	
16	22/05/20 12:08	General View		Load JPG	☒	
17	22/05/20 12:08	General View		Load JPG	☒	
18	22/05/20 12:08	General View		Load JPG	☒	
19	22/05/20 12:08	General View		Load JPG	☒	
20	22/05/20 12:08	General View		Load JPG	☒	
21	22/05/20 12:08	General View		Load JPG	☒	

Assessment Reports				1 per page	☒
No	Finalized On	Auto Insure Pte Ltd (HQ) (Woodlands)		Thumbnail	Print
22	17/06/20 15:39	Dismantled Parts		Load JPG	☒
23	17/06/20 15:39	Dismantled Parts		Load JPG	☒
24	17/06/20 15:39	Dismantled Parts		Load JPG	☒
25	17/06/20 15:39	Dismantled Parts		Load JPG	☒
26	17/06/20 15:39	Dismantled Parts		Load JPG	☒
27	17/06/20 15:39	Dismantled Parts		Load JPG	☒
28	17/06/20 15:39	After Repair Photo		Load JPG	☒
29	17/06/20 15:39	After Repair Photo		Load JPG	☒
30	17/06/20 15:39	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Auto Insure Pte Ltd (HQ) (Woodlands)		Thumbnail	Print
1	20/05/20 15:48	E-filed GIA report		Load PDF	
2	20/05/20 15:55	AUDATEX ESTIMATE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20005856/QQF3S2**Date:** 24/06/2020**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN16275219033

Claimant Vehicle No : SMS2666L **Insured Vehicle No :** SKF4243C

Date of Loss: 19/05/2020 Nature of Claim: TP Claim No: SNM20D201950/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS2666L**

Make & Model: TOYOTA VELLFIRE, 2.5 ELEGANCE MOONROOF (A) Engine No: 2AR2194864

Reg. Date: 19/02/2020 (Man. Year: 2019) Chassis No: JTNGF3DH708023786

Colour: Black Odometer: 9029 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,010.00	700.00	310.00	30.69
Miscellaneous Items	42.00	0.00	42.00	100.00
Labour	142.80	113.40	29.40	20.59
Paintwork Labour	192.10	192.10	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,386.90	1,005.50	381.40	27.50
+ GST 7.00/7.00% (S\$)	97.08	70.39	26.69	27.49
Nett Amount (S\$)	1,483.98	1,075.89	408.09	27.50

INSPECTION

Date of Assignment: 20/05/2020 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 21/05/2020 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)
6 Marsiling Lane
Singapore 739145

Estimated Period of Repair: 1.0 days

Adjuster: OI SUN PIN**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2020)

Parts: M1-MPV TOYOTA VELLFIRE 2.5 ELEGANCE MOONROOF (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS2666L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		1,010.00 F	-
2	1		*FRONT NUMBER PLATE	Dented	-	*25.00 F
3	1		*FRT NO PLATE BRKT	Crushed	-	*35.00 F
4	1		*GRILLE	Cracked	-	*610.00 F
5	1		*LWR RADIATOR GRILLE	Serviceable	-	*- F
6	1		*FIXED SUNDRY PARTS PRICE	Necessary	-	*30.00 F
					Total Parts (\$\$)	1,010.00 700.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	42.00	-
Sub Total (\$\$)			42.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	PAINTWORK	New	192.10	-
2	PAINT WORK: LABOUR COST.	New	-	134.40
3	PAINT WORK: MATERIAL COST.	New	-	57.70
<u>Labour Items</u>				
4	LABOUR	New	142.80	113.40
Gross Labour Cost (\$\$)			334.90	305.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >