

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
 3 Anson Road  
 #16-00 Springleaf Tower  
 Singapore 079909

From: LKK Auto Consultants Pte Ltd  
 51 Ubi Ave 1 #01-25  
 Paya Ubi Industrial Park  
 Singapore 408933

Attn: Pauline Tham Date: 22 May 2020

**Preliminary Advice**

Insured Vehicle No	:	SKF4243C		
TP Vehicle No	:	SMS2666L	Accident Date	: 19/05/2020
Make	:	TOYOTA VELLFIRE	Assignment Date	: 20/05/2020
Date of Inspection	:	21/05/2020	Est. Duration of Repair	: 1
Inspection At	:	AUTO INSURE PTE LTD (HQ) (WOODLANDS) 6 MARSILING LANE SINGAPORE 739145		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 1,386.90
Revised Amount	:	S\$ 389.90
Check Items (Estimated)	:	S\$ 610.00
Total	:	S\$ 999.90
Lump Sum Repair		:

**Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :