



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG19021715/Eyf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

ATTN : NG HAI CHUAN

Date : 27-05-2020



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 6300G	Veh. Inspected	SKX 2847D
Policy No.	1800018789	Coverage (\$)	0.00
Claim No.	4310838133SG	Excess (\$)	0.00
Assign From	NG HAI CHUAN	Assign Date	21/05/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600062194	Colour	BLACK
Odometer	62147	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	YOKOHAMA	5 mm
L/H Front Tyre	225/65 R17	YOKOHAMA	5 mm
R/H Rear Tyre	225/65 R17	MICHELIN	5 mm
L/H Rear Tyre	225/65 R17	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/12/2019	Inspection Date	10/12/2019
Survey held at	8 KAKI BUKIT AVE 4 #04-20 PREMIER		
Repairer	A-TEC AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
--	-----------------------