

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com /teamautopl@gmail.com

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SJU 6724 B**
 Made : Lexus
 Model : IS250
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front door LH RH	1	\$ 1,242.30	\$ 978.00 1,242.30
2	Front door lock assy	1	\$ 328.40	\$ 328.40
3	Front door lock striker	1	\$ 84.20	\$ 84.20
4	front door outer handle w/sensor	1	\$ 412.60	\$ 412.60
5	Front door weatherstrip	1	\$ 241.30	\$ 241.30
6	Front door trimboard	1	\$ 423.60	\$ 423.60
7	Front door frame rubber	1	\$ 108.50	\$ 108.50
12	Rear door LH RH	1	\$ 1,182.40	\$ 922.00 1,182.40
13	Rear door weatherstrip	1	\$ 210.30	\$ 210.30
14	Rear door lock assy	1	\$ 314.50	\$ 314.50
15	Rear door lock striker	1	\$ 84.20	\$ 84.20
16	Rear door trimboard	1	\$ 418.30	\$ 418.30
17	Rear door frame rubber	1	\$ 108.50	\$ 108.50
18	Rear shock absorber	2	\$ 354.00	\$ 354.00
19	Rear lower arm	2 1	\$ 315.60	\$ 249.85 315.60
20	Rear upper arm	2	\$ 289.40	\$ 289.40
21	Rear knuckle arm	2	\$ 452.80	\$ 452.80
22	Rear knuckle arm bearing	2 1	\$ 187.20	\$ 187.20
8	Rear fender	1	\$ 1,085.30	\$ 1045.00 1,085.30
10	Rear fender inner cowling	1	\$ 185.60	\$ 185.60
23	Rear bumper	1	\$ 1,147.60	\$ 890.00 1,147.60
24	Rear bumper side retainer	2	\$ 65.00 104.80	\$ 130.00 209.60
Parts Sub Total :				\$ 4638.05 9,386.20
10% Discount				\$ 463.81 938.62
PARTS TOTAL :				\$ 4,174.25 8,447.58

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Front door sealant	1	\$ 80.00	\$ 30.00 80.00	NEC
3	Front door trimboard clips	1	\$ 50.00	\$ 30.00 50.00	NEC
4	Rear fender sealant	1	\$ 80.00	\$ 30.00 80.00	NEC
5	Rear fender inner cowling clips	1	\$ 50.00	\$ 30.00 50.00	NEC
6	Rear door sealant	1	\$ 80.00	\$ 30.00 80.00	NEC
7	rear door trimboard clips	1	\$ 50.00	\$ 30.00 50.00	NEC
8	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC
9	Alloy rim <i>local repair</i>	1	\$ CUT 850.00	\$ 200.00 850.00	RX
10	Tyre	1	\$ 350.00	\$ 350.00	NDX
SPECIAL NETT TOTAL :				\$ 410.00 1,720.00	

Nos.	LABOUR	S\$	
1	R&R front door component	\$ 60.00 120.00	/
2	R&R Rear door component	\$ 60.00 120.00	/
3	R&R front undercarriage parts.	\$ 80.00 150.00	/
4	R&R front tyre and balancing	\$ 30.00 120.00	/
5	Wheel alignment.	\$ 60.00 120.00	/
6	Upholstery	\$ 200.00	NNX
7	Check wiring	\$ 60.00 120.00	✓
8	Panel beat	\$ 800.00 1,800.00	✓
9	Spray paint	\$ 1000.00 1,800.00	✓
10	Rust proofing	\$ 30.00 -100.00	
LABOUR TOTAL :		\$ 2180.00 4,650.00	

Survey 21/5/2020 Resurvey 22/5/2020
 1410 hrs TGLim Lim
 TGLim Lim

Lump sum repair
 Repair days 6

PARTS TOTAL : \$ 8,447.58
 SPECIAL NETT TOTAL : \$ 1,720.00
 LABOUR TOTAL : \$ 4,650.00
GRAND TOTAL : \$ 14,817.58

Parts 4,174.25
 s/n 410.00
 Labour 2180.00
 6764.25
 @ 20% 1352.85
 5411.40

L/S 5400/2

TGLim Lim
 22/5/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: