



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

20/5/2020

Vehicle:

SMT3229D

Make / Model:

HONDA FIT

Chassis No:

GK3-3418676

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / DD	1	\$ 592.60	\$ 592.60
2	REAR BUMPER SIDE RETAINER LH / DR	1	\$ 16.90	\$ 16.90
3	REAR BUMPER SIDE RETAINER RH / DR	1	\$ 16.90	\$ 16.90
4	REAR BUMPER BRACKET LH X	1	\$ 75.00	\$ 75.00
5	REAR BUMPER BRACKET RH X	1	\$ 75.00	\$ 75.00
6	REAR BUMPER GRILLE COVER LH ?	1	\$ 28.50	\$ 28.50
7	REAR BUMPER GRILLE COVER RH X	1	\$ 28.50	\$ 28.50
8	REAR BUMPER CENTER MOUDLING (UPPER) / CUT	1	\$ 130.60	\$ 130.60
9	REAR BUMPER SIDE MOUDLING LH ?	1	\$ 36.50	\$ 36.50
10	REAR BUMPER SIDE MOUDLING RH X	1	\$ 36.50	\$ 36.50
11	REAR BUMPER MOUDLING (LOWER) ?	1	\$ 127.50	\$ 127.50
12	REAR TAILLAMP LH / CUT	1	\$ 237.40	\$ 237.40
13	REAR TAILLAMP LOWER BRACKET LH X	1	\$ 32.60	\$ 32.60
14	REAR TAILLAMP RH X	1	\$ 237.40	\$ 237.40
15	REAR TAILLAMP LOWER BRACKET RH X	1	\$ 32.60	\$ 32.60
16	REAR TAILGATE / DD	1	\$ 914.00	\$ 914.00
17	REAR TAILGATE LOCK / BT	1	\$ 78.60	\$ 78.60
18	REAR TAILGATE LOCK CATCH X	1	\$ 30.10	\$ 30.10
19	REAR END PANEL / DD	1	\$ 590.00	\$ 590.00
20	REAR END PANEL TOP GARNISH / CUT	1	\$ 143.50	\$ 143.50
21	REAR BOOT WEATHER STRIPE / TN	1	\$ 102.30	\$ 102.30
22	REAR TAILGATE EMBLEM FIT / NC	1	\$ 55.70	\$ 55.70
23	REAR TAILGATE SWITCH X	1	\$ 65.60	\$ 65.60
24	REAR TAILGATE INNER TRIM BOARD / CUT	1	\$ 127.90	\$ 127.90
				\$ 3,812.20
			Less 20%	\$ 762.44
			Total	\$ 3,049.76
S/Nett items:				
1	REAR REVERSE SENSOR / ST	1 SET	\$ 250.00	\$ 250.00
2	REAR REVERSE CAMERA X	1 SET	\$ 300.00	\$ 300.00
3	REAR BUMPER CLIP / NC	1 SET	\$ 80.00	\$ 80.00
4	REAR END PANEL GARNISH CLIP / NC	1 SET	\$ 30.00	\$ 30.00
5	FLOOR PANEL SEALANT X	1	\$ 50.00	\$ 50.00
6	END PANEL SEALANT / NC	1	\$ 50.00	\$ 50.00
7	REAR WINDSCREEN GLASS SEALANT / NC	1	\$ 60.00	\$ 60.00
8	MISCELLANEOUS X	1	\$ 200.00	\$ 200.00
				\$ 1,020.00

200

30

10

30

40

SMT3229D

Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	REMOVE AND REFIX REAR UPHOLSTERY	1	\$ 150.00	\$ 150.00
4	REPAIR AND STRAIGHTEN CHASSIS FRAME	1	\$ 200.00	\$ 200.00
5	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 150.00	\$ 150.00
6	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 150.00	\$ 150.00
7	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00
8	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
10	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
11	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
				\$ 3,180.00
Parts Replacement Amount				\$ 4,069.76
Total Amount for Labour				\$ 3,180.00
Total Amount				\$ 7,249.76

30
30
X
X
30
50
120
X
30
600
700

Steve (LKK) M AL
21/5/20, 2.00pm
5 Lys
L/S
My M sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: