

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 9702T - AIG

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Not Notified
*11 Sep 8***ROEL****SHB 9702T - ROEL**

VF1ABL15AUC273242

RENAULT

LATITUDE

30.01.17

AIG

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Bn</i> 968.78 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 303.60 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 703.14 X
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 139.81 X
5	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 159.40 X
6	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 116.47 X
7	1	BUMPER RETAINER FRT RH	\$	<i>Cnt</i> 116.47 ✓
8	1	BUMPER SUPPORT FRT RH	\$	<i>Sn</i> 18.37 X
9	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 363.71 X
10	1	RADAITOR GRILLE	\$	<i>Sn</i> 1,313.68 X
11	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>R</i> 173.32 X
12	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i> 1,041.35 X
13	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 477.37 X
14	1	LOWER ARM RH	\$	<i>Sn</i> 527.51 X
15	1	KUNCKLE ARM RH	\$	<i>Sn</i> 651.53 X
16	1	ABSORBER FRT RH	\$	<i>Sn</i> 277.34 X
17	1	ABSORBER DUST COVER	\$	<i>Sn</i> 175.93 X
18	1	BONNET	\$	<i>R</i> 1,493.56 X
19	1	WIPER RESERVOIR	\$	<i>Sn</i> 173.60 X
20	1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 91.78 X
21	1	HEADLAMP RH	\$	<i>Cnt</i> 911.10 ✓
22	1	HEADLAMP PANEL FRT RH L70Y	\$	<i>R</i> 117.04 X
23	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95 ✓
24	1	FENDER WHEELARCH FRT RH	\$	<i>Cnt</i> 107.33 ✓
25	1	FENDER BRACKET FRT RH L70Y	\$	<i>Sn</i> 26.26 X
26	1	DOOR PANEL FRT RH	\$	<i>R</i> 2,188.20 X
27	1	DOOR SEAL FRT RH	\$	<i>Sn</i> 55.30 X
28	1	DOOR MIRROR RH	\$	<i>Sn</i> 1,141.08 X

TOTAL	\$	14,435.97
10%	\$	1,443.60
	\$	12,992.37

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>R</i> 66.00 ✓
---	------	-------------------	----	------------------

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 9702T - AIG

2	1SET	WHEELARCH CLIP RH	\$	<i>Nn</i>	66.00	✓
3	1	DOOR STICKER "Trans-cab"	\$	<i>Nn</i>	80.00	✓
4	1	DOOR STICKER "Classic"	\$	<i>Nn</i>	30.00	✓
5	1	CAP HUB RH FRT	\$	<i>Ph</i>	35.00	✓
6	1	RIM RH FRT	\$		385.00	?
7	1	TYRE RH FRT	\$	<i>Ph</i>	330.00	✓

TOTAL	\$	992.00
TOTAL PARTS	\$	13,984.37

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	<i>4000</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
Putty and spray painting of the affected	\$	3,000.00	<i>4400</i>
To check brake efficiency, final checking and testing.	\$	380.00	<i>Nn</i> ✓
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	<i>Nn</i> ✓
To check steering geometry and computer wheel alignment	\$	220.00	<i>600</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	<i>Nn</i> ✓
Towing Fees	\$	120.00	<i>Nn</i> ✓
To transfer of tire, rim and on wheel	\$	170.00	?
To rust-proofing of the affected areas.	\$	170.00	<i>300</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "No Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TOTAL	\$	7,790.00
Over All Total	\$	21,774.37

10 Days
2 days