



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM20005875/Ega3q2 Date: 02/03/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDG 71K	Veh. Inspected	SMK 5796S	
Policy No.	GA453949	Coverage (\$)	0.00	
Claim No.	S0M02O97	Excess (\$)	0.00	
Assign From		Assign Date	21/05/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS PLUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDZS3EU70J035790	Colour	GREY	
Odometer	91339 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R16	DUNLOP	5 mm	
L/H Front Tyre	225/60 R16	DUNLOP	5 mm	
R/H Rear Tyre	225/60 R16	DUNLOP	5 mm	
L/H Rear Tyre	225/60 R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/05/2020	Inspection Date	21/05/2020	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	