



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 20/5/2020

Vehicle: SMK5796S

Make / Model: TOYOTA PRIUS

Chassis No: JTDZS3EU70J035790

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / <i>OD</i>	1	\$ 630.54	\$ 630.54
2	REAR BUMPER LOWER LIP / <i>CH</i>	1	\$ 728.90	\$ 728.90
3	REAR BUMPER SIDE RETAINER LH / <i>BR</i>	1	\$ 113.60	\$ 113.60
4	REAR BUMPER REINFORCEMENT / <i>BT</i>	1	\$ 350.50	\$ 350.50
5	REAR BUMPER BRACKET LH / <i>NN</i>	1	\$ 115.30	\$ 115.30
6	REAR BUMPER REFLECTOR LH / <i>BR</i>	1	\$ 80.60	\$ 80.60
7	REAR TAILGATE / <i>NN</i>	1	\$ 1,180.60	\$ 1,180.60
8	REAR TAILGATE EMBLEM HYBRID / <i>NN</i>	1	\$ 89.40	\$ 89.40
9	REAR TAILGATE EMBLEM PRIUS / <i>NN</i>	1	\$ 82.30	\$ 82.30
10	REAR TAILLAMP LH / <i>BR</i>	1	\$ 690.50	\$ 690.50
11	REAR TAILLAMP INNER PANEL LH / <i>NN</i>	1	\$ 280.40	\$ 280.40
12	REAR TAILLAMP LOWER BRACKET LH / <i>BR</i>	1	\$ 89.10	\$ 89.10
13	REAR TAILLAMP CLIPS / <i>MC</i>	1	\$ 9.80	\$ 9.80
14	REAR END PANEL / <i>Repair</i>	1	\$ 660.20	\$ 660.20
15	REAR END PANEL TOP GARNISH / <i>NN</i>	1	\$ 225.10	\$ 225.10
16	REAR WINDSCREEN GLASS MOULDING / <i>NN</i>	1	\$ 128.30	\$ 128.30
17	REAR FENDER LH / <i>R</i>	1	\$ 850.30	\$ 850.30
				\$ 6,305.44
			Less 25%	\$ 1,576.36
			Total	\$ 4,729.08
S/Nett items:				
1	REAR REVERSE SENSOR / <i>BR</i>	1 SET	\$ 250.00	\$ 250.00
2	REAR REVERSE CAMERA / <i>NN</i>	1 SET	\$ 300.00	\$ 300.00
3	REAR BUMPER CLIP / <i>MC</i>	1 SET	\$ 80.00	\$ 80.00
4	REAR END PANEL GARNISH CLIP / <i>NN</i>	1 SET	\$ 30.00	\$ 30.00
5	REAR WINDSCREEN GLASS SEALANT / <i>NN</i>	1	\$ 50.00	\$ 50.00
6	END PANEL SEALANT / <i>NN</i>	1	\$ 50.00	\$ 50.00
7	REAR BUMPER TOP RUBBER / <i>MC</i>	1	\$ 120.00	\$ 120.00
8	MISCELLANEOUS / <i>NN</i>	1	\$ 200.00	\$ 200.00
				\$ 1,080.00

3F

523 ✓

580 ✓

✓

✓

×

68 ✓

×

×

×

630 ✓

×

68 ✓

✓

×

×

×

×

2342.90

-25%

1757.17

299

30

80

310

SMK5796S

Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	REMOVE AND REFIX REAR UPHOLSTERY	1	\$ 150.00	\$ 150.00
4	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 100.00	\$ 100.00
5	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 150.00	\$ 150.00
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00
7	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
8	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
9	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
10	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
				\$ 2,530.00
			Parts Replacement Amount	\$ 5,809.08
			Total Amount for Labour	\$ 2,530.00
			Total Amount	\$ 8,339.08

30
30
X
X
X
X
X
30
500
450

1040

Steve (LKK) WL M

21/5/20, 2.00pm

4 days

L/S

M. M. M

P - 1757.17

N - 310

L - 1040

3107.17

L/S - 2485.73

= 2500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: