



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 20/5/2020

Vehicle: SMK5796S

Make / Model: TOYOTA PRIUS

Chassis No: JTDZS3EU70J035790

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / <i>OD</i>	1	\$ 630.54	\$ 630.54
2	REAR BUMPER LOWER LIP / <i>cut</i>	1	\$ 728.90	\$ 728.90
3	REAR BUMPER SIDE RETAINER LH / <i>DR</i>	1	\$ 113.60	\$ 113.60
4	REAR BUMPER REINFORCEMENT / <i>DT</i>	1	\$ 350.50	\$ 350.50
5	REAR BUMPER BRACKET LH <i>X</i>	1	\$ 115.30	\$ 115.30
6	REAR BUMPER REFLECTOR LH / <i>BR</i>	1	\$ 80.60	\$ 80.60
7	REAR TAILGATE <i>X</i>	1	\$ 1,180.60	\$ 1,180.60
8	REAR TAILGATE EMBLEM HYBRID <i>X</i>	1	\$ 89.40	\$ 89.40
9	REAR TAILGATE EMBLEM PRIUS <i>X</i>	1	\$ 82.30	\$ 82.30
10	REAR TAILLAMP LH / <i>BR</i>	1	\$ 690.50	\$ 690.50
11	REAR TAILLAMP INNER PANEL LH <i>X</i>	1	\$ 280.40	\$ 280.40
12	REAR TAILLAMP LOWER BRACKET LH / <i>BR</i>	1	\$ 89.10	\$ 89.10
13	REAR TAILLAMP CLIPS / <i>MC</i>	1	\$ 9.80	\$ 9.80
14	REAR END PANEL / <i>X R</i>	1	\$ 660.20	\$ 660.20
15	REAR END PANEL TOP GARNISH <i>X</i>	1	\$ 225.10	\$ 225.10
16	REAR WINDSCREEN GLASS MOULDING <i>X</i>	1	\$ 128.30	\$ 128.30
17	REAR FENDER LH <i>X R</i>	1	\$ 850.30	\$ 850.30
				\$ 6,305.44
			Less 25%	\$ 1,576.36
			Total	\$ 4,729.08
S/Nett items:				
1	REAR REVERSE SENSOR / <i>DR</i>	1 SET	\$ 250.00	\$ 250.00
2	REAR REVERSE CAMERA <i>X</i>	1 SET	\$ 300.00	\$ 300.00
3	REAR BUMPER CLIP / <i>MC</i>	1 SET	\$ 80.00	\$ 80.00
4	REAR END PANEL GARNISH CLIP <i>X</i>	1 SET	\$ 30.00	\$ 30.00
5	REAR WINDSCREEN GLASS SEALANT <i>X</i>	1	\$ 50.00	\$ 50.00
6	END PANEL SEALANT <i>X</i>	1	\$ 50.00	\$ 50.00
7	REAR BUMPER TOP RUBBER <i>X</i> / <i>MC</i>	1	\$ 120.00	\$ 120.00
8	MISCELLANEOUS <i>X</i>	1	\$ 200.00	\$ 200.00
				\$ 1,080.00

299

30

80

SMK5796S

Labour to:					
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	30
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00	30
3	REMOVE AND REFIX REAR UPHOLSTERY	1	\$ 150.00	\$ 150.00	X
4	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 100.00	\$ 100.00	X
5	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 150.00	\$ 150.00	X
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00	X
7	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00	X
8	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	30
9	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00	✓
10	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00	450
				\$ 2,530.00	
		Parts Replacement Amount		\$ 5,809.08	
		Total Amount for Labour		\$ 2,530.00	
		Total Amount		\$ 8,339.08	

Steve (LKK) WL M
 21/5/20, 2.00pm
 4 days
 L/S
 My AL My

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: