

15/5/2020

INS. CASE OWNER:

Fong Fong

CC 6/AIG14023471

1 Kh 93

LKK:

IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

09/12/14

Date / Time:

09/12/14

Registered in Merimen:

18/12/14

Pre-assign / CCU / FTE



Insured Vehicle No.:

866 5290B

Name of Insured:

Skill Tec Metal Engineering

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 05/12/14

Claim No.:

212878852454

Policy No.:

2100392402

Make / Model:

Toyota

Place of Accident:

Yishun Central / Blk 925
Car Park

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age: Yan Chun An

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: 9673 7636

(V/L: YES / NO Insured Liability:

% Final ? Yes / No

SJP7452E



INSRS:

WSP: Alan's United

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	FOR CSO ONLY:	STAGE	DATE / PIC
18/12/14	Is driver the owner? (YES / NO)	Finalisation:	
Vic	If NO, Driver Name / Age:	Email AIG for OI GIA:	
	Driver's Own Vehicle Number:	Apt letter to OI:	
	Insurance Company:	Call OI:	29/06/15 Kenneth Tan
	SJP7452E - CS/TP14020/88/Kalle 3, DOA: 07/08/14	After call ltr to OI:	(LKK) (QA)
	866 5290B - X	Type Report:	
	01 REPORTED TP REPAIR.	Prepare Invoice:	CUH 177
		Others:	
29/06/15	- Any video recording as evidence	Documentation Check List:	Handler Typist
29/06/15 @ 5:29pm	Spoken to OJD. OJD confirmed accident details.	OI Apt Ltr:	
	Informed OJD of TP claim, OJD agree to settle and aware that his NCD will be affected.	Authorisation To Act:	
	- OJD do not have any video recording.	Release Voucher:	
	- OJD stated accident location has CCTV.	Final Repair Bill:	
	- OJD Mandarin speaking.	Car Rental Invoice:	
	- KNU TUE AFTER LETTER WENT OUT.	LTA / GIA:	
	- TO REVIEW CLAIM.	Medical Bill:	
8/7/15 @ 12:05pm	OJD call in. OJD received letter. OJD Do Not Agree to settle	Approval Email:	
	& Dispute TP claim. OJD stated, he was not at fault.	Payment Breakdown Form:	
@ 12:30pm	Call OJD, No Response	Others:	
@ 4:45pm	Call OJD,		
9/7/15 @ 9:11am	Call OJD,		
14/7/15 @ 5:10pm	Spoken to OJD Mr Yan Chun An, Informed OJD if he wishes to obtain the CCTV footage. OJD has to file for a Police Investigation Report & follow by apply/approval from Town Council/HDB for the NSCP CCTV.		
16/7/15 @ 2:20pm	OJD call in. OJD mentioned it was impossible to obtain CCTV footage from HDB. OJD mentioned filed TP claim & approve \$600, OJD unaware is (50-50% or 20-80%).		
07-11-16	OJD workshop @ Serve You Motor Services - Ms Elaine Shja - 92343188, UNDER NORMAL CIRCUMSTANCES. % should have repaired tp BUT IF TP SUSTAINED DAMAGE AT THE RIGHT REAR CORNER AND TP INSURER AGREED TO Complicating Version ABSORB 50% I BELIEVE OJD'S STATEMENT		
FINAL SETTLEMENT	Date: 15/12/14	BOLA S/N No.:	NH
Repair Cost:	SS IS CREDIBLE. 50 Final Liability: 50 % (Agreed / Assessed)	If NO or B 28, Ass. Lia:	
Loss of Rental:	SS TO REJECT TP CLAIM. ADVISE AIG TO CLOSE THE FILE.		
Loss of Use:	SS - (\$ x days)	1) Claim status: Normal/Reject/Private Settle	
Disbursement:		2) Report Format: WP REPORT TP INACCURACY	
Legal Cost:	SS -	3) Survey fee: \$310.00	
Total:	SS -	Global Sum: SS	

ASS. REC. BY:

REF:

ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

STP 7452E

Yr Regn:

11, 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Impreza

c.c

1994

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

126842

T/Radio: Insured / Std / NI / NA

Eng/No:

JF1GD BK1435G 055546

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Continental

225/45 R17

R: Archiles

235/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

5/12/14

D.O.I.

9/12/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

FINISHED FOR (UNCONFIRMED) LG \$1,650.00 WITH 4 DAYS
 CRED: \$ 776.56 / 32%
 CHECK TRUCK: \$ 121.60

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG14023471/Khe3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 18-12-2014



Code : AIG

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SGG 5290B	Veh. Inspected	SJP 7452E
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	18/12/2014

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.	Accident Date	05/12/2014	Inspection Date	18/12/2014
	Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

Remarks

5a.

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estates #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGG5290B (AIG)

Accident Date : 05-12-2014

Date : 09-12-2014

Our Ref : SJP7452E / CHAN

YONG WEI HANG

C/O ALAN'S UNITED AUTO PTE LTD

BLK 7, SIN MING ROAD

01-76

SINGAPORE 575642

Not Authored
21 Sep 8?
Returning After Paint
4 days

ESTIMATE COST OF REPAIR FOR SUBARU IMPREZA STI SJP7452E

1 PC	REAR BUMPER FASCIA	<i>CRA</i>	\$760.10	✓
1 PC	REAR O/S BUMPER SIDE RETAINER	<i>Dis</i>	\$62.00	✓
1 PC	REAR O/S TAILLAMP	<i>Co</i>	\$496.60	✓
1 PC	REAR BOOT COMPARTMENT SPARE TANK		\$152.00	?
			\$1,470.70	
		LESS 20%	\$294.14	
			\$1,176.56	

\$1,176.56

1 PC REAR BUMPER LAMINATION STICKER

Ne \$400.00 SN *2501a*

TO PUTTY AND SPRAY REAR BUMPER & END PANEL LOWER

\$450.00 *4000*

TO PANEL BEATING DAMAGED PARTS, REMOVE & RENEW REAR BUMPER, ALIGN & ADJUST REPLACED PARTS

\$400.00 *3500*

\$2,426.56

Singapore Dollars Two Thousand Four Hundred Twenty Six And Cents Fifty Six Only

SEARCH: SEARCH INFORMATION

Search

Entity


Public Accountant

[Home](#) | [Explore eServices](#)[Buy Information](#)[About Bizfile](#)[FAQ](#)

SKILLTEC METAL ENGINEERING

Search

ANNOUNCEMENT : There are no recent Announcements

[Read More](#) >  SINGPASS
LOG-IN Payment Cart
You have 0 items[Learn more about SingPass](#)

WICKACCESS

[Transaction Status Enquiry](#)
[Product Authentication](#)
[Value Added Services](#)
[FA/QI Enquiry](#)
[Refund Application](#)
[Expiry Date Enquiry](#)
(Business/LP)
[Refund Enquiry](#)
[PA/PAE Enquiry](#)

Enter Entity Name or Unique Entity Number (UEN)

SKILLTEC METAL ENGINEERING



Captcha (Enter the above 5 characters)

Search

EntityPAFilter by  Reset

Showing 1 - 3 of 3 Rows

Show 3

« Back Next »


Entity Name : SKILLTEC METAL ENGINEERING(n.k.a)

NAM LEONG ENGINEERING(f.k.a)

UEN:

43823400J

Address:

10 ADMIRALTY STREET #02-71 NORTH LINK
BUILDING SINGAPORE 757695 [View Map](#)

Entity Status:

TERMINATED

Compliance Rating:

-

[Buy Information](#)


Entity Name : SME METAL ENGINEERING PTE. LTD.(n.k.a)

SKILLTEC METAL ENGINEERING PTE. LTD.(f.k.a)

UEN:

201013195N

Address:

10 ADMIRALTY STREET #02-70 NORTH LINK
BUILDING SINGAPORE 757695 [View Map](#)

Entity Status:

STRUCK OFF

Compliance Rating:

-


[Buy Information](#)

Entity Name : SKILLTEC METAL ENGINEERING

UEN:

53180548D

Address:

10 ADMIRALTY STREET #02-71 NORTH LINK
BUILDING SINGAPORE 757695 [View Map](#)

Entity Status:

LIVE

Compliance Rating:

-

[Buy Information](#)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 8 November, 2016 12:52 PM
To: Loh, Chee-Heng
Cc: Admin A; Vic (LKKAUTO)
Subject: Your Ref: 2128788524SG_ACCIDENT INVOLVING VEHICLES SGG 5290B AND SJP 7452E ON 05/12/2014

Your Ref: 2128788524SG
Our Ref: CC6/AIG14023471/Khe3

Dear Chee Heng,

ACCIDENT INVOLVING VEHICLES SGG 5290B AND SJP 7452E ON 05/12/2014

We refer to the above matter.

We had spoken to the Insured driver on 29/06/2015 where he was informed of the TP claim and liability issues. Later on, when Insured driver received our letter, he further denied liability and doesn't want to settle the claim.

Based on our opinion, this is a conflicting version. Our Insured driver has no further evidence to provide and he was also making a claim against TP insurer but no update from his workshop.

As such, we had requested to TP repairer for any evidence to support their client's version but till date, we haven't received any feedback yet.

In view of no activity from TP, we would intend to close this matter and submit WP report.

For your approval and/or further instructions.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG14023471/Khe3

1st July 2015

SKILLTEC METAL ENGINEERING

10 ADMIRALTY STREET
#02-70, NORTH LINK BUILDING
SINGAPORE 757695

ATTN: YAN CHUN AN

Dear Sir/Madam,

ACCIDENT INVOLVING SGG 5290B AND SJP 7452E ON 05/12/2014

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 15/07/2015, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Kenneth Tan
Case Handler

DID: 6841 2132

FAX: 6741 4108

Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Revoked / No settlement

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by adjuster]																					
Insured:	Skilltec Metal Engineering, NRIC: 53180548D																							
Main Claimant:	YONG WEI HANG, NRIC: S8302859I																							
Vehicle Reg. No.:	SJP7452E	Date of Loss:	05/12/2014 16:00 - :59																					
Claim Type:	TP / 2128788524SG	Policy/Cover Note No.:	2100392402 (Comprehensive) Coverage: 16/11/2014 - 15/11/2015																					
Vehicle Reg. No. (Insured):	SGG5290B	Policy No. (Claimant):	5066588471																					
		Excess:	S\$																					
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686																							
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Crystabelle-GP - 6419-1946] Crystabelle-GP.Tan@aig.com																							
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel: 64307877																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/12/2014]																							
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail																				
There are no mail for this case.																								
<div><div></div><div>ALL ASSOCIATED TASKS</div><div><div>View All</div><div>Search Tasks</div><div>Create New Task</div><div>Complete</div></div><table><thead><tr><th>Due Date</th><th>Priority</th><th>Type</th><th>Task Group</th><th>Subject</th><th>Handler</th><th>Assigned By</th><th>Completed On</th><th>Created On</th><th>Done?</th></tr></thead><tbody><tr><td colspan="10">No results.</td></tr></tbody></table></div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SJP7452E (2128788524SG)
[SGG5290B]
TP
YONG WEI HANG
Dec 5 2014 4:00PM
[Skilltec Metal Engineering]
Alan's United Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
2	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
3	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
4	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
5	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
6	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
7	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
8	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
9	18/12/14 16:45	General View		Load JPG	<input checked="" type="checkbox"/>
10	18/12/14 16:45	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
11	18/12/14 16:45	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/12/14 16:44	TP ESTIMATE		Load PDF	
2	18/12/14 16:44	TP GIA REPORT		Load PDF	
3	08/11/16 14:20	EMAIL TO AIG		Load PDF	
4	10/11/16 09:24	Email from AIG CSE		Load PDF	
5	10/11/16 15:59	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	18/12/14 17:59	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG14023471/KHA3Q2

Date: 10/11/2016

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100392402
Claimant Vehicle No : SJP7452E Insured Vehicle No : SGG5290B
Date of Loss: 05/12/2014 Nature of Claim: TP Claim No: 2128788524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP7452E
Make & Model: SUBARU WRX, 2.5 (M) Engine No: HIDDEN
Reg. Date: 01/11/2005 (Man. Year: 2005) Chassis No: JF1GDBKH35G055544
Colour: Black Odometer: 126842 km
Engine Capacity: 1994 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 235/45 R17
Front Left Side: Continental 6 mm Rear Left Side: Archilles 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Archilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,576.56	1,304.96	271.60	17.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	750.00	100.00	11.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,426.56	2,054.96	371.60	15.31
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,426.56	1,650.00	776.56	32.00
+ GST 7.00/7.00% (S\$)	169.86	115.50	54.36	32.00
Nett Amount (S\$)	2,596.42	1,765.50	830.92	32.00

INSPECTION

Date of Assignment: 09/12/2014
Date Inspected: 09/12/2014 Inspected At: Alan's United Auto Pte Ltd (HQ)
Estimated Period of Repair: 4.0 days Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Cracked	760.10 FL	*760.10 FL
2	1		*REAR O/S BUMPER SIDE RETAINER	Distorted	62.00 FL	*62.00 FL
3	1		*REAR O/S TAILLAMP	Cut	496.60 FL	*496.60 FL
4	1		*REAR BOOT COMPARTMENT SPARE TANK	*Check	152.00 FL	*- FL
5	1		*REAR BUMPER LAMINATION STICKER	Necessary	400.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,870.70	1,568.70
- List Item Discount on L Items 20.00/20.00% (\$)	294.14	263.74
Total Parts (\$)	1,576.56	1,304.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY REAR BUMPER & END PANEL LOWER	New	450.00	400.00
2	TO PANEL BEATING DAMAGED PARTS ,REMOVE & RENEW REAR BUMPER,ALIGN & ADJUST REPLACED PARTS	New	400.00	350.00
Gross Labour Cost (S\$)			850.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >