

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estates #01-76, Singapore 575642.
 Tel: 6453 8686 (3 Lines) Fax: 6459 6550
 Company Reg. No.: 201113667N
 GST Reg. No.: 201113667N

Vehicle Insured : SGG5290B (AIG)
 Accident Date : 05-12-2014

Date : 09-12-2014

Our Ref : SJP7452E / CHAN

YONG WEI HANG
 C/O ALAN'S UNITED AUTO PTE LTD
 BLK 7, SIN MING ROAD
 # 01-76
 SINGAPORE 575642

Not Authorized
 L/Sy 87
 Resurvey After Painting
 4 days

ESTIMATE COST OF REPAIR FOR SUBARU IMPREZA STI SJP7452E

1 PC	REAR BUMPER FASCIA	CDA	\$760.10
1 PC	REAR O/S BUMPER SIDE RETAINER	D/S	\$62.00
1 PC	REAR O/S TAILLAMP	W	\$496.60
1 PC	REAR BOOT COMPARTMENT SPARE TANK	PU	\$152.00
			\$1,470.70
		LESS 20%	\$294.14
			\$1,176.56

\$1,176.56

1 PC REAR BUMPER LAMINATION STICKER

\$400.00 SN 2501A

TO PUTTY AND SPRAY REAR BUMPER & END PANEL LOWER

\$450.00 400

TO PANEL BEATING DAMAGED PARTS, REMOVE & RENEW REAR BUMPER, ALIGN & ADJUST REPLACED PARTS

\$400.00 350

\$2,426.56

Singapore Dollars Two Thousand Four Hundred Twenty Six And Cents Fifty Six Only

P1054.96
 SN 250
 L 750
 2054.96
 410.59
 1643.57

L/S
 1600 / ok
 @
 4 days
 KENNEDY P/S CONFIRM
 TKS.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: