

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estates #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGG5290B (AIG)

Date : 09-12-2014

Accident Date : 05-12-2014

Our Ref : SJP7452E / CHAN

YONG WEI HANG

C/O ALAN'S UNITED AUTO PTE LTD

BLK 7, SIN MING ROAD

# 01-76

SINGAPORE 575642

*Not Authorized*  
*L/Sing 8?*  
*Resurvey After Paint*  
*4 days*

## ESTIMATE COST OF REPAIR FOR SUBARU IMPREZA STI SJP7452E

|      |                                  |            |                   |   |
|------|----------------------------------|------------|-------------------|---|
| 1 PC | REAR BUMPER FASCIA               | <i>CRT</i> | \$760.10          | ✓ |
| 1 PC | REAR O/S BUMPER SIDE RETAINER    | <i>Dis</i> | \$62.00           | ✓ |
| 1 PC | REAR O/S TAILLAMP                | <i>Cor</i> | \$496.60          | ✓ |
| 1 PC | REAR BOOT COMPARTMENT SPARE TANK |            | \$152.00          | ? |
|      |                                  |            | \$1,470.70        |   |
|      |                                  |            | LESS 20%          |   |
|      |                                  |            | \$294.14          |   |
|      |                                  |            | <u>\$1,176.56</u> |   |

\$1,176.56

|                                                                                           |                                |                   |                  |
|-------------------------------------------------------------------------------------------|--------------------------------|-------------------|------------------|
| 1 PC                                                                                      | REAR BUMPER LAMINATION STICKER | \$400.00          | SN <i>250511</i> |
| TO PUTTY AND SPRAY REAR BUMPER & END PANEL LOWER                                          |                                | \$450.00          | <i>4000</i>      |
| TO PANEL BEATING DAMAGED PARTS, REMOVE & RENEW REAR BUMPER, ALIGN & ADJUST REPLACED PARTS |                                | \$400.00          | <i>3500</i>      |
|                                                                                           |                                | <u>\$2,426.56</u> |                  |

Singapore Dollars Two Thousand Four Hundred Twenty Six And Cents Fifty Six Only