

(LRC (Mr Adrian))



Let Auto Consultants hence notify
the insurer of the following:

- To remove, replace or spray paint on the body parts damaged (to) during repair.
- Parts prices are subject to confirmation

Kaki Bukit Autohub
2 Kaki Bukit Ave 2
#01-17 / #01-18 (Heavy Vehicle #01-08 / Spray Painting #02-27)
Singapore 417921
Tel No. : +65 6842 0092 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Acknowledged by Repairer

Signature

Date

Reg. No. : 200616038C

Grab Rentals Pte Ltd
18 SIN MING LANE #01-08
MIDVIEW CITY
Singapore 573960

Contact: 66550005 97286866

TPFWD

Jasper

ESTIMATE

Repair Code: CLM16249

Accident Date: 21/05/2020

Vehicle No.: SLW2552Y

Model: HONDA VEZEL HYBRID 1.5 AUTO

Chassis/Eng#: RU31222435/LEB5922448

(fwd)

(1/6/2020 sunny)

4 days

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR TAILGATE <i>Dented</i>	L	1	\$ 953.30	\$ 953.30
2	REAR TAILGATE WEATHER STRIP <i>3 x 4</i>	L	1	\$ 96.80	\$ 96.80
3	REAR TAILGATE MECHANISM LOCK <i>3 x 1</i>	L	1	\$ 180.00	\$ 180.00
4	REAR TAILGATE 'HYBRID' EMBLEM <i>3 x 1</i>	L	1	\$ 75.80	\$ 75.80
5	REAR TAILGATE 'VEZEL' EMBLEM <i>3 x 1</i>	L	1	\$ 56.20	\$ 56.20
6	REAR TAILGATE WINDSCREEN INNER SEAL <i>3 x 1</i>	L	2	\$ 50.00	\$ 100.00
7	REAR TAILGATE WINDSCREEN MOULDING <i>3 x 1</i>	L	2	\$ 50.00	\$ 100.00
8	REAR BUMPER <i>Dented</i>	L	1	\$ 762.70	\$ 762.70
9	REAR BUMPER SIDE RETAINER L/R <i>2 x 1</i>	L	2	\$ 23.00	\$ 46.00
10	REAR BUMPER LOWER COVER <i>Dented</i>	L	1	\$ 250.00	\$ 250.00
11	REAR END PANEL INNER TOP GARNISH <i>Dented</i>	L	1	\$ 98.00	\$ 98.00
12	REAR END PANEL BUZZLE SENSOR <i>crushed</i>	L	1	\$ 85.20	\$ 85.20

Subtotal before discount:

Percentage discount 20%:

Sub-total 1

\$ 2,804.00

\$ 560.80

\$ 2,243.20

13	REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	S	1	\$ 80.00	\$ 80.00
14	REAR BUMPER REVERSE SENSOR <i>Dented</i>	S	1	\$ 250.00	\$ 250.00
15	REAR BUMPER CLIPS - SET <i>new</i>	S	1	\$ 50.00	\$ 50.00

Subtotal before discount:

Percentage discount 0%:

Sub-total 2

Parts-total

\$ 380.00

0.00

\$ 380.00

\$ 2,623.20

LABOUR

1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	\$ 50.00
2	To remove, reinstall tailgate windscreen.	\$ 120.00
3	To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	\$ 80.00
4	To re-spray painting on the change bodyparts, rear portion, and where consistent to the accident.	\$ 650.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	\$ 550.00
6	To apply anti-rust chemical on repaired and replaced panel.	\$ 50.00
7	To remove, refix tailgate mechanism & check for function.	\$ 80.00

Labour total

Parts & Labour total

\$ 1,580.00

\$ 4,203.20

total: 3281.76

1/s: 2.61k 04Days