

(08/11/13) wef

REF:

CC6/A1620005913/UK93

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Veh No:

FBG8259H

Yr Regn:

11/12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

SYM VS150A

C.C. 150

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

76628

T/Radio: Insured / Std / NI / NA

Eng/No:

RFGHV 15WYC5004764

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-12

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

R/Bal.

6

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

2/5/120

D.O.I.

26/5/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear, O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

3k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

2

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

623M

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

17/11/12 491 not 2509

27/11/12 confirmed 1/5 @ 1400 with Raymond.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$)

) S + RS, _ SI

☐

: Interview (\$)

) Photos

☐

: Tech. Invs (\$)

) Others

☐

: Weekend (\$)

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 36105

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

*not Authorized
date
L/S \$1400
5 days
take photo of damage
26/5/20*

DATE : 14/05/2020
CLAIM NO. : 11551
POLICY NO. : V0107670
FROM : RAYMOND

VEHICLE NO. : FBG8259H
MAKE/MODEL : SYM / VS150

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOARD FLOOR	REPLACE	1.00	\$44.50	44.50
2	COVER INNER MUDGUARD REAR	Replace	1.00	\$22.30	22.30
3	BALANCER HANDLE P/N: 40328	REPLACE	1.00	\$15.00	15.00
4	BALL BEARING P/N: 27530 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED	Replace	1.00	\$2.00	2.00 X
5	BALL STEEL P/N: 48508	REPLACE	1.00	\$0.50	0.50 X
6	BEARING STEERING CONE UPPER P/N: 48503	REPLACE	1.00	\$7.50	7.50 X
7	BELLY PAN (BLACK) P/N: 65465	REPLACE	1.00	\$131.80	131.80
8	BOX REAR FIBRE STD (23X18X18) TL-V2 P/N: 38504 - WAIVED	Replace	1.00	\$430.00	430.00 X
9	BRACKET UNDER FORK P/N: 64334	Replace	1.00	\$178.20	178.20 X
10	COVER FRONT (WHITE) P/N: 64508	Replace	1.00	\$119.00	119.00 X
11	COVER INNER FRONT P/N: 57767	Replace	1.00	\$140.00	140.00
12	COVER TAIL LH	Replace	1.00	\$150.00	150.00 X

*36105

*Respray rear box
Respray front fork
Respray rear cover
Rear license plate also ✓*

bigSAFE₃



Address: No. 6, Dafu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
13	COVER TAIL RH	Replace	1.00	\$150.00	150.00
14	DUST SEAL P/N: 48506	Replace	1.00	\$4.20	4.20 X
15	FORK FRONT LH ASSY P/N: 42231	Replace	1.00	\$251.00	251.00 X
16	LABOUR P/N: 06766	Replace	8.00	\$45.00	360.00
17	LEVER BRAKE RH P/N: 39942	Replace	1.00	\$20.50	20.50
18	LIGHT TAIL ASSY P/N: 64074	Replace	1.00	\$406.00	406.00
19	MIRROR RH P/N: 63640	Replace	1.00	\$67.20	67.20
20	MUDGUARD FRONT P/N: 65464	Replace	1.00	\$98.00	98.00 X
21	MUDGUARD REAR P/N: 66578	Replace	1.00	\$27.00	27.00
22	PIPE EXHAUST ASSY P/N: 40205	Replace	1.00	\$812.00	812.00 X
23	RACE BALL P/N: 50142	Replace	1.00	\$10.80	10.80 X
24	RACE BALL P/N: 48505	Replace	1.00	\$10.80	10.80 X
25	RACE BOTTOM CONE P/N: 48504	Replace	1.00	\$9.80	9.80 X
26	REFLECTOR MUDGUARD REAR	Replace	1.00	\$8.00	8.00
27	SEAL DUST WASHER P/N: 48509	Replace	1.00	\$4.20	4.20 X
28	SHOCK ABSORBER REAR LH P/N: 63644	Replace	1.00	\$111.50	111.50 ?
29	SHOCK ABSORBER REAR RH P/N: 63645	Replace	1.00	\$79.60	79.60 ?
30	SIDE COVER LOWER RH P/N: 64429	Replace	1.00	\$42.00	42.00
31	STICKER (SINGAPORE POST) BOX REAR P/N: 40798	Replace	1.00	\$30.00	30.00

SUB TOTAL

\$3,743.40

GST @ 7 %

\$262.04

GRAND TOTAL (SGD)

\$4,005.44

50% deposit required before ordering of parts.

Quote is preliminary, bike at base. Validity: 30 days

*36105 *

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*36105 *

bizSAFE₃



Address: No. 6, Dafu lane 4, Singapore 539410 | **Telephone:** +65 6281 6520 | **Web:** www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

NO. : 37171

- Rev. 1

Supplementary 1 To QTN: 36105

DATE : 26/11/2020

CLAIM NO. : 11551

POLICY NO. : V0107670

FROM : RAYMOND

VEHICLE NO. : FBG8259H
MAKE/MODEL : SYM / VS150

S/N	Description	Action	Qty	Unit Price	Amount
1	SPRAY PAINT COVER TAIL LH	Spray	1.00	\$45.00	45.00 ✓
2	SPRAY PAINT MUDGUARD FRONT	Spray	1.00	\$45.00	45.00 ✓
3	SPRAY PAINT REAR BOX	Spray	1.00	\$210.00	210.00 ✓
4	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	Replace	1.00	\$15.00	15.00 ^{S.N} ✓
SUB TOTAL					\$315.00
GST @ 7 %					\$22.05
GRAND TOTAL (SGD)					\$337.05

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*37171 *

bizSAFE₃

