



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

NO : 36105

DATE : 14/05/2020

CLAIM NO. : 11551

POLICY NO. : V0107670

FROM : RAYMOND

VEHICLE NO. : FBG8259H
MAKE/MODEL : SYM / VS150

*not Authorized
d/bn
H/S
5 days.
take photo of damage
26/5/20*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOARD FLOOR	REPLACE	1.00	\$44.50	CU 44.50
2	COVER INNER MUDGUARD REAR	Replace	1.00	\$22.30	BRO 22.30
3	BALANCER HANDLE P/N: 40328	REPLACE	1.00	\$15.00	scr 15.00
4	BALL BEARING P/N: 27530 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED	Replace	1.00	\$2.00	11 2.00 X
5	BALL STEEL P/N: 48508	REPLACE	1.00	\$0.50	11 0.50 X
6	BEARING STEERING CONE UPPER P/N: 48503	REPLACE	1.00	\$7.50	11 7.50 X
7	BELLY PAN (BLACK) P/N: 65465	REPLACE	1.00	\$131.80	CU 131.80
8	BOX REAR FIBRE STD (23X18X18) TL-V2 P/N: 38504 - WAIVED	Replace	1.00	\$430.00	2 430.00 X
9	BRACKET UNDER FORK P/N: 64334	Replace	1.00	\$178.20	scr 178.20 X
10	COVER FRONT (WHITE) P/N: 64508	Replace	1.00	\$119.00	2 119.00 X
11	COVER INNER FRONT P/N: 57767	Replace	1.00	\$140.00	CU 140.00
12	COVER TAIL LH	Replace	1.00	\$150.00	2 150.00 X

*36105 Respray rear box
Respray front fork
Respray rear cover
Rear license plate spro ✓

biSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
13	COVER TAIL RH	Replace	1.00	\$150.00	150.00
14	DUST SEAL P/N: 48506	Replace	1.00	\$4.20	4.20 X
15	FORK FRONT LH ASSY P/N: 42231	Replace	1.00	\$251.00	251.00 X
16	LABOUR P/N: 06766	Replace	8.00	\$45.00	360.00
17	LEVER BRAKE RH P/N: 39942	Replace	1.00	\$20.50	20.50
18	LIGHT TAIL ASSY P/N: 64074	Replace	1.00	\$406.00	406.00
19	MIRROR RH P/N: 63640	Replace	1.00	\$67.20	67.20
20	MUDGUARD FRONT P/N: 65464	Replace	1.00	\$98.00	98.00 X
21	MUDGUARD REAR P/N: 66578		1.00	\$27.00	27.00
22	PIPE EXHAUST ASSY P/N: 40205	Replace	1.00	\$812.00	812.00 X
23	RACE BALL P/N: 50142	Replace	1.00	\$10.80	10.80 X
24	RACE BALL P/N: 48505	Replace	1.00	\$10.80	10.80 X
25	RACE BOTTOM CONE P/N: 48504	Replace	1.00	\$9.80	9.80 X
26	REFLECTOR MUDGUARD REAR	Replace	1.00	\$8.00	8.00
27	SEAL DUST WASHER P/N: 48509	Replace	1.00	\$4.20	4.20 ?
28	SHOCK ABSORBER REAR LH P/N: 63644	Replace	1.00	\$111.50	111.50 ?
29	SHOCK ABSORBER REAR RH P/N: 63645		1.00	\$79.60	79.60 ?
30	SIDE COVER LOWER RH P/N: 64429	Replace	1.00	\$42.00	42.00
31	STICKER (SINGAPORE POST) BOX REAR P/N: 40798	Replace	1.00	\$30.00	30.00

SUB TOTAL

\$3,743.40

GST @ 7 %

\$262.04

GRAND TOTAL (SGD)

\$4,005.44

50% deposit required before ordering of parts.

Quote is preliminary, bike at base. Validity: 30 days

*36105 *


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

blSAFE₃CERT NO. 2002-1-0383
ISO 1001:2015

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

Quotation Nos. 36105

(Page 3 of 3)

S/N Description

Action

Qty

Unit Price

Amount

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email : L&A Fax and will bear a computer generated signature

*36105 *

bizSAFE



Address: No. 8, Delfi Lane 4, Singapore 539419 | Telephone: +65 6281 5520 | Web: www.bhh.com.sg
Fax (Main): +65 6281 2820, (Spare Parts): +65 6280 7530, (Insurance Project): +65 6284 2980, (Accounts): +65 6281 6750