



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CENTRAL NARCOTICS BUREAU

Ref : CS/CNB18009556/R1qbe2

CORPORATE SERVICES DIVISION BLK B POLICE  
CANTONMENT COMPLEX 393 NEW BRIDGE  
ROAD SINGAPORE 088763

Date : 01-11-2018



ATTN : MUHAMMAD ASYRAF

Code : CNB

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLL 9162B
Policy No.	HOMCNBECI18300468	Coverage (\$)	0.00
Claim No.	HOMCNBEPO18300474	Excess (\$)	0.00
Assign From	MUHAMMAD ASYRAF	Assign Date	24/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	CHEVROLET	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	KL1JA69E9GK351372	Colour	BLACK
Odometer	10969	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	KUMHO	6 mm
L/H Front Tyre	205/60 R16	KUMHO	6 mm
R/H Rear Tyre	205/60 R16	KUMHO	6 mm
L/H Rear Tyre	205/60 R16	KUMHO	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date		Inspection Date	31/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

--	--



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. SLL 9162B

S/N	ITEM DESCRIPTION	PARTS				MAN- HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	Boot Lid Cover	1	Bent	\$1,230.00	\$1,230.00	
1.2	Boot Lid Hinges LH & RH	2	Servicable	\$50.00	\$0.00	
1.3	RHS Boot Lamp	1	Broken	\$310.00	\$310.00	
1.4	RHS Tail Lamp	1	Cracked	\$310.00	\$310.00	
1.5	LHS Tail Lamp	1	Broken	\$310.00	\$310.00	
1.6	Boot Lid Emblem	1	Necessary	\$85.00	\$85.00	
1.7	"CHEVROLET" Emblem	1	Necessary	\$25.00	\$25.00	
1.8	"CRUZE IS" Emblem	1	Necessary	\$25.00	\$25.00	
1.9	Car Boot Inner Lock	1	Bent	\$85.00	\$85.00	
1.10	Car Boot Rubber Seal	1	Cut	\$200.00	\$200.00	
1.11	Rear Bumper	1	Deformed	\$1,050.00	\$1,050.00	
1.12	Rear Bumper Retainers (Side)	2	Necessary	\$15.00	\$30.00	
1.13	Rear Bumper Retainers (Centre)	1	Necessary	\$52.00	\$52.00	
1.14	Rear Bumper Retainers (Below Tail Lamp)	2	Servicable	\$28.00	\$0.00	
1.15	Rear Bumper Centre Garnish	1	Deformed	\$105.00	\$105.00	
1.16	Rear Bumper Side Garnish	2	Deformed	\$55.00	\$110.00	
1.17	Rear End Panel	1	Bent	\$805.00	\$805.00	
1.18	Rear End Panel Garnish	1	Deformed	\$60.00	\$60.00	
1.19	Reverse Sensor	1	Not Working	\$200.00	\$200.00	
1.20	Rear RHS Tow Eye Cover	1	Missing	\$10.00	\$10.00	
1.21	Rear Bumper Reinforcement	1	Bent	\$260.00	\$260.00	
1.22	Luggage Cover	1	Servicable	\$280.00	\$0.00	
1.23	Rear Number Plate & Casing	1	Missing	\$50.00	\$50.00	
1.24	Front Bumper	1	Deformed	\$1,205.00	\$1,205.00	
1.25	Front RH Bumper Retainer	1	Necessary	\$10.00	\$10.00	
1.26	Front Number Plate & Casing	1	Bent	\$50.00	\$50.00	
1.27	Spare Tyre Panel	1	Repair	\$1,110.00	\$0.00	

SCOPE OF REPAIRS						
1.1	<b>Car Boot:</b>					12
	Remove & Replace Boot Lid Cover					
	Remove & Replace Boot Lid Cover Hinges					
	Remove & Replace Boot Lid Emblem					
	Remove & Replace "CHEVROLET" Emblem					
	Remove & Replace "CRUZE IS" Emblem					
	Remove & Replace Car Boot Inner Lock					
	Remove & Replace Car Boot Rubber Seal					
	Remove & Replace Luggage Cover					
	Putty & Spray Paint for Boot Lid Cover					
1.2	<b>Rear Boot Lamp &amp; Tail Lamp:</b>					3
	Remove & Replace RHS Boot Lamp & Tail Lamp					
	Remove & Replace LHS Tail Lamp					
	Wiring for Replaced Boot & Tail Lamp					
1.3	<b>Rear Bumper:</b>					12
	Remove & Replace Rear Bumper					
	Remove & Replace Both Side Rear Bumper Retainers (Side, Centre & Below Tail Lamp)					
	Remove & Replace Rear Bumper Centre Garnish					
	Remove & Replace Rear Bumper Side Garnish					
	Remove & Replace Rear Bumper Reinforcement					
	Remove & Replace Rear RHS Tow Eye Cover					
	Remove & Replace Reverse Sensor					
	Wiring for Reverse Sensor					
	Putty & Spray Paint for Rear Complete Bumper					
1.4	<b>Rear End Panel:</b>					12
	Remove & Replace Rear End Panel					
	Remove & Replace Rear End Panel Garnish					
1.5	<b>Front Bumper:</b>					6
	Remove & Replace Front Bumper					
	Remove & Replace Front RH Bumper Retainer					
	Putty & Spray Paint for Front Complete Bumper					
1.6	<b>Number Plates:</b>					1
	Remove & Replace Front & Rear Number Plate					
1.7	<b>Rear RH &amp; LH Panel:</b>					6
	Panel Beating for Rear RH & LH Panel					
	Putty & Spray Paint for Rear RH & LH Panel					
1.8	<b>Spare Tyre Panel:</b>					10
	Remove & Replace Spare Tyre Panel					

	Putty & Spray Paint for Spare Tyre Panel				
COSTING		TOTAL PARTS COST		\$6,577.00	
		TOTAL MAN-HOUR			62

Registration No. SLL 9162B

Vehicle Inspected By

MRB

MOHD RASUL BIN MOHD YUNUS  
 AMSOE, AMIRTE, AMSAE-A, M. MATAI  
 Automotive Assessor



ADRIAN LING WAI PING  
 B. Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI  
 Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.