

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

27/5/2020

MS First Capital Insurance Limited

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SMA2153U

QTY	List Items	AMOUNT
1	1 PC FONT BUMPER <i>De/cut</i>	\$ 1,120.00 ✓
2	1 SET FRONT BUMPER CLIPS <i>rec</i>	\$ 50.00 ✓
3	1 PC FRONT BUMPER LH SIDE RETAINER <i>11</i>	\$ 30.00 X
4	1 PC HEADLAMP LH <i>11</i>	\$ 1,070.00 X
5	1 PC FRONT LH FENDER <i>70/90/1</i>	\$ 350.00 ✓
6	1 SET FRONT LH FENDER CLIPS <i>rec</i>	\$ 49.00 ✓
		\$ 2,669.00
		\$ 2,135.20
7	TUFF KOTE	\$ 80.00 <i>30</i>
8	TO PUTTY AND SPRAY PAINTING	\$ 680.00 <i>400</i>
9	CHECK HARNESS	\$ 30.00 <i>20</i>
10	TO REMOVE AND RENEW PARTS.	\$ 480.00 <i>300</i>
		\$

not Arthur
2/5
1600
3 days.

9-1589
20%
1-1288.2
2-750.00
2025.2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: 1 of 1

Date: