

DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 18 May 2020)
 Parts: 143 FORD FOCUS 1.6 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SGY7358H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT <i>bt /</i>			
2	1		*REAR BOOT LOGO <i>ne /</i>	20.00	0.00	*2,300.00 FL <i>1888</i>
3	1		*REAR BOOT EMBLEM FOCUS <i>ne /</i>	20.00	0.00	*186.00 FL <i>80</i>
4	1		*REAR BOOT EMBLEM TITANIUM <i>ne /</i>	20.00	0.00	*165.00 FL <i>80</i>
5	1		*REAR BOOT GARNISH <i>crn /</i>	20.00	0.00	*192.00 FL <i>68</i>
6	1		*REAR BOOT LOCK <i>X SUL</i>	20.00	0.00	*493.00 FL
7	1		*REAR WINDSCREEN MOULDING <i>ne /</i>	20.00	0.00	*214.00 FL <i>X</i>
8	1		*REAR WINDSCREEN SEALANT <i>ne /</i>	20.00	0.00	*244.00 FL
9	1		*REAR BUMPER <i>crn /</i>	0	0.00	<i>60</i> *80.00 FS
10	1		*REAR BUMPER CENTRE TOP BRACKET <i>? crn /</i>	20.00	0.00	*1,725.00 FL
11	1		*REAR BUMPER REINFORCEMENT <i>? bt /</i>	20.00	0.00	*192.00 FL <i>180</i>
12	2		*REAR BUMPER RETAINER L+R <i>X SUL</i>	20.00	0.00	*680.00 FL <i>550</i>
13	10		*REAR BUMPER CLIPS <i>ne /</i>	20.00	0.00	*150.00 FL <i>X</i>
14	1		*REAR BUMPER LOWER <i>crn /</i>	20.00	0.00	*107.00 FL <i>40</i>
15	2		*REAR BUMPER SENSOR <i>? not /</i>	20.00	0.00	*564.00 FL <i>230</i>
16	2		*REAR BUMPER SENSOR BRACKET <i>? X SUL</i>	20.00	0.00	*590.00 FL <i>420</i>
17	1		*REAR NUMBER PLATE LAMP <i>X SUL</i>	20.00	0.00	*150.00 FL <i>X</i>
18	1		*REAR NUMBER PLATE <i>scr /</i>	20.00	0.00	*155.00 FL <i>X</i>
19	1		*REAR BOOT RUBBER <i>ne /</i>	0	0.00	<i>35</i> *80.00 FS
20	1		*REAR PANEL - REPAIR	20.00	0.00	*346.00 FL
21	1		*REAR FLOOR PANEL - REPAIR	20.00	0.00	-
22	1		*REAR FENDER L+R - REPAIR	20.00	0.00	-

F=Franchise part, S=SpocNett, L=ListItemDisc.

Sub Total (\$\$) 8,593.00
 - List Item Discount on L Items (\$\$) 1,690.60
 Total Parts (\$\$) 6,902.40

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

S/N-95
6341
20%
5072.80

ates on Miscellaneous Items
no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CUT & WELD REAR END PANEL. TO REPAIR REAR FLOOR PANEL, REAR FENDER L+R. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	500 600.00
2	TO SPRAY AFFECTED AREAS	New	600 700.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	120 160.00
4	TO REMOVE & REFIX REAR BOOT MECHANISM, CHECK & TEST WIPER MOTOR & CENTRE LOCKING SYSTEM	New	60 100.00
5	TO REMOVE & REFIX LUGGAGE COMPARTMENT SIDE COVER, SIDE GARNISH CARPET AND OTHER ATTACHMENT PARTS	New	40 80.00
6	TO EUST PROOF AFFECTED AREAS	New	30 50.00
Gross Labour Cost (S\$)			1,690.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
5 days
4/5
01/06/2020 @ 1410
Reby after repair

5672.80

95.00

1350.00

6517.80

20%

5214.24

Repair limit \$2,500
5 days