

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

26/05/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP FWD.

Jasper

Accident date: 26/05/2020

Estimated repair cost for vehicle no: SMD2312L KIA CERATO K3 17'

CHASSIS: KNAFX411MJ5742058

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>new</i>		\$1,297.00	+
2	2	Rear Boot Lid Hinge <i>3 new</i>	\$66.00	\$132.00	+
3	2	Rear Boot Lid Shock Absorber <i>new</i>	\$85.00	\$170.00	+
4	1	Rear Boot Lid Emblem Logo <i>2</i>		\$48.00	✓
5	1	Rear Boot Lid Forte Logo <i>1 new</i>		\$43.00	✓
6	1	Rear Boot Lid K3 Logo		\$40.00	✓
7	1	Rear Boot Lid C&C Logo		\$55.00	✓
8	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00	+
9	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$35.00	\$70.00	+
10	2	Rear Boot Lid Side Reflector <i>RH ut</i>	\$177.00	\$354.00	177
11	1	Rear Boot Lid Lock <i>new</i>		\$122.00	+
12	1	Rear Boot Lid Weatherstrip <i>new</i>		\$98.00	+
13	1	Rear Boot Lid Inner Trim Board <i>2 new</i>		\$225.00	+
14	8	Rear Boot Lid Inner Trim Board Clip <i>1 new</i>	\$6.50	\$52.00	+
15	1	Rear Boot Lid Reverse Camera (Special Nett) <i>new</i>		\$680.00	+
16	2	Rear Taillamp <i>RH ut</i>	\$696.00	\$1,392.00	696
17	4	Rear Taillamp Clip <i>new</i>	\$8.00	\$32.00	+
18	2	Rear Taillamp Panel <i>new</i>	\$103.00	\$206.00	+
19	1	Rear Bumper <i>Delivered</i>		\$688.00	✓
20	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	30
21	1	Rear Bumper Lower Lid <i>Delivered</i>		\$286.00	✓

22	2	Rear Bumper Side Retainer	new	\$38.00	\$76.00	✓
23	2	Rear Bumper Side Reflector	new RH cancelled	\$114.00	\$228.00	✓ 1/4
24	2	Rear Bumper Reverse Sensor	Don't	\$155.00	\$310.00	✓
25	1	Rear Bumper Reinforcement	could		\$338.00	✓
26	1	Rear End Panel	Don't		\$385.00	✓
27	1	Rear End Panel Top Garnish	could		\$108.00	✓
28	1	Rear Exhaust	Best		\$880.00	✓ 591

Subtotal :- \$8,430.00

3885

3586.50

Labour charges

Gum	\$60.00	X
To remove & refit reverse sensor	\$100.00	50
To remove & refit reverse camera	\$180.00	X
To check wiring	\$100.00	30
Tuff kote	\$150.00	60
Towing fee	1540	\$150.00 X
Panel beating	\$1,400.00	700
Spray painting	\$1,200.00	700

Subtotal :- \$3,340.00

Total:- \$11,770.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/s 26/05/20
05 Days

Total: 5126.50

L/s A.K

4.1K