

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005939/KGA3Q2

Date: 26/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMK7205T	Insured Vehicle No :	SHB4201E
Date of Loss: 22/05/2020	Nature of Claim: TP	Claim No: MCT20050151

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK7205T		
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Engine No:	2ZR0C94876
Reg. Date:	23/04/2019 (Man. Year: 2018)	Chassis No:	JTDZS3EU70J037152
Colour:	Metallic Black	Odometer:	149721 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Arivo 9 mm	Rear Left Side:	Arivo 9 mm
Front Right Side:	Arivo 9 mm	Rear Right Side:	Arivo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,924.64	1,604.17	1,320.47	45.15
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	160.00	40.00	120.00	75.00
Paintwork Labour	431.90	431.90	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,527.54	2,087.07	1,440.47	40.83
Approved Total (Overridden) (S\$)		2,076.07		
(S\$)	3,527.54	2,076.07	1,451.47	41.15
+ GST 7.00/7.00% (S\$)	246.93	145.32	101.61	41.15
Nett Amount (S\$)	3,774.47	2,221.39	1,553.08	41.15
+ Loss of Use (4.0 x S\$88.00/day) (S\$)		352.00		
Nett Liability (S\$)		2,573.39		

INSPECTION

Date of Assignment:	26/05/2020 Present Location:	City Auto Pte Ltd (HQ)
Date Inspected:	26/05/2020 Inspected At:	City Auto Pte Ltd (HQ)
		160 Sin Ming Drive #05-01,, Sin Ming
		AutoCity,
		Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2020)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK7205T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*R/DOOR MIRROR ASSY	Broken	1,373.70 FL	*1,373.70 FL
2	1	NA	*R/DOOR MIRROR COVER	Missing	98.64 FL	*98.64 FL
3	1	NA	*R/F DOOR WINDOW	Mtg Broken	478.61 FL	*478.61 FL
4	1	NA	*R/F OUT WINDOW SEAL	Scratched / Cut	140.15 FL	*140.15 FL
5	1	NA	*R/F UPP D/F RAME FOIL	Not Necessary	87.60 FL	*- FL
6	1	NA	*R/F WING BADGE	Necessary	47.80 FL	*47.80 FL
7	1	NA	*RIGHT FRONT DOOR	Repair	1,429.30 FL	*- FL
					Sub Total (\$\$)	3,655.80
					- List Item Discount on L Items 20.00/25.00% (\$\$)	731.16
					Total Parts (\$\$)	2,924.64
						1,604.17

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	325.00	325.00
2	Total Paint Materials	New	106.90	106.90
Labour Items				
3	Total Panel/Mechanical Labour	New	160.00	40.00
Gross Labour Cost (\$\$)			591.90	471.90

Report was unsubmitted during this print-out.

< END OF ESTIMATES >