

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBH 8783E

Date : 24.05.2020

Vehicle Model : TOYOTA HIACE

Chassis : JTFHT02P100245188

Accident Date : 22.05.2020

TP Ins. **AIG**

Original Reg Date : 16.10.2018

ESTIMATE

1	2 pcs	Bonnet Hinges				LH-X, RH-H
2	1 pc	Bonnet Lock				X
3	1 pc	Wiper Garnish				cut
4	1 pc	Front Corner Panel RH				bt
5	1 pc	Headlamp RH				conv
6	1 set	Headlamp Clips				re
7	1 set	Headlamp Bottom Clips (Big)				rec
8	1 pc	Headlamp Base Panel RH				?
9	1 pc	Front Grille				dis
10	1 set	Front Grille Clips				re
11	1 pc	Front Bumper				de
12	2 pcs	Front Bumper Side Retainers				RH-de
13	1 set	Front Bumper Clips				rec
14	1 pc	Front Bumper Reinforcement				?
15	1 pc	Front Bumper Bracket RH				dis
16	1 pc	Front Chassis Frame Member RH				?
17	1 pc	Front Bumper Lower Grille				de
18	1 pc	Front Bumper Fog Lamp Cover				cut
19	1 pc	Front Bumper Fog Lamp Bracket				dis
20	1 pc	Wing Harness Cover Box RH				?
21	1 set	Wing Harness RH				?
22	1 pc	Air Cleaner Box Assy RH				?
23	1 pc	Front Windscreen				ing
24	1 pc	Front Windscreen Moulding				re
25	1 pc	Front Floor Panel				Rx
26	1 pc	Front Door Pillar Outer RH				?
27	1 pc	Front Door Pillar Inner RH				?
28	1 pc	Front Wheel Arch Mudguard RH				?
29	1 pc	Front Wheel Arch Mudguard Inner Garnish				?
30	1 set	Front Wheel Arch Mudguard Inner Garnish Clips				?
31	1 pc	Front Door Pillar Frame Weatherstrip RH				re

32	1 pc	Brake Booster Pump				✓
33	1 pc	Radiator				X
34	1 pc	Air Con Condenser				X
35	1 pc	Dashboard				?
36	1 pc	Dashboard Inner Cross Member				✓

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No. : GBH 8783E

B/F

1	1 pc	Rear Side Panel RH				buc ✓
2	1 pc	Rear Side Panel Inner Panel RH				RY
3	2 pcs	Rear Bumper Side Retainer				RH de ✓
4	1 pc	Taillamp RH				cut ✓
5	1 pc	Taillamp Inner Sealer				ner ✓
6	1 pc	Rear Shock Absorber RH				X
7	1 pc	Rear Wheel Bearing RH				✓

Less 25%

Special Nett

1	1 pc	Front Windscreen ERP Bracket			30.00	ner ✓
2	1 pc	Front Windscreen Sealant			60.00	ner ✓
3	1 pc	Front Windscreen Inner Seal			50.00	ner ✓
4	1 set	Front Windscreen Solar Film			420.00	?
5	1 pc	Front Windscreen Black Sticker			150.00	ner 80
6	1 pc	Front Windscreen Sticker 29			100.00	ner 40
7	1 pc	Front Number Plate			40.00	bt ✓
8	1 pc	Front Bumper Lower Spoiler			900.00	de ✓ 500.
9	1 pc	Front Door Company Lettering			40.00	ner ✓
10	1 pc	Front Wheel Rim RH			350.00	bt ✓ 250
11	1 pc	Front Tyre RH			380.00	put ✓ 80%
12	1 set	Wheel Rim Mud Cap			300.00	cut ✓ 200
13	1 set	Front Door Side Protector			350.00	de ✓ 200
14	1 set	Front Door Sun Visor			250.00	ner ✓ 150.
15	1 set	Center Pillar Air Grille			200.00	cut ✓ 100

16	1 pc	Radiator Cooler		40.00	X
17	1 set	Rear Bumper Fog Lamp		500.00	CNA ✓
18	1 set	Front Shock Absorber		1,200.00	?
19	1 set	Front Shock Absorber Bush		180.00	?
20	1 pc	Bonnet		900.00	bt ✓
21	1 pc	Rear Bumper (Fiber)		950.00	de ✓
22	1 pc	Brake Oil		60.00	?

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No. : GBH 8783E

B/F

-

Labour charge

1	Panel Beating	2,500.00	1800
2	Spray painting	2,300.00	1800
3	Check Wiring	100.00	40.
4	Anti rust	180.00	120.
5	Remove and install front windscreen	140.00	120.
6	Remove and install front door parts	90.00	60.
7	Remove and install dashboard	350.00	250? plus.
8	Remove and install air con	120.00	X
9	Remove and install front and rear undercarriage	600.00	380 plus?
10	Check four wheels alignment	90.00	60.
11	Remove and install carpet, seat, front upholstery rear interior	200.00	120.
12	Remove and install Brake master pump.	150	? plus.
		Less 20%	-
		Lump sum	-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
 WP' 26/5/20 2/650.
 Lump sum
 Resurvey after repair
 17 days
 tanpin @ lkkmp.com.