LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Date: 28 May 2020

Preliminary Advice

Insured Vehicle No : SGZ3626E

TP Vehicle No : SHB5233G Accident Date : 20/05/2020

Make : TOYOTA PRIUS Assignment Date : 27/05/2020

Date of Inspection : 26/05/2020 Est. Duration of Repair : 7 days

Inspection At : SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,737.35
Revised Amount	:S\$	8,260.29
Check Items (Estimated)	:S\$	3,365.70
Total	:S\$	11,625.99

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP