



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 22/5/2020
 Vehicle: GBD7259E
 Make / Model: VOLKSWAGON TRANSPORTER
 Chassis No: WAUZZZ8POCA122534

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BONNET X R	1	\$ 1,877.05	\$ 1,877.05
2	LH FRONT FENDER X R	1	\$ 575.00	\$ 575.00
3	LH FRONT DOOR X R	1	\$ 1,560.55	\$ 1,560.55
4	LH FRONT MIRROR / RR	1	\$ 764.45	\$ 764.45
5	LH FRONT MIRROR COVER / RR	1	\$ 312.75	\$ 312.75
				\$ 5,089.80
				Less 10%
				\$ 508.98
				Total
				\$ 4,580.82
S/Nett items:				
1	LH FRONT DOOR COMPANY STICKER / MC	1	\$ 20.00	\$ 20.00
2	MISCELLANEOUS X MI	1	\$ 200.00	\$ 200.00
				\$ 220.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND TRANSFER ALL LH FRONT DOOR FITTING	1	\$ 150.00	\$ 150.00
3	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 100.00	\$ 100.00
4	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00
5	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
6	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 900.00
7	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
				\$ 2,050.00
			Parts Replacement Amount	\$ 4,800.82
			Total Amount for Labour	\$ 2,050.00
			Total Amount	\$ 6,850.82

1077.70
 - 10%
 969.48

30/-
 X
 X
 X
 30/-
 700/-
 490/-
 1160

Steve (LKK) MR AL
 L/S
 26/5/20, 4.30 pm
 2 days
 My AL sly

P- 969.48
 N- 20
 L- 1160
 2149.48

L/S - 1719.58
 = 1700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: