



CAS GARAGE PTE LTD

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE
(MOTOR CLAIMS DEPARTMENT)

Address: NO 8, SHENTON WAY, #24-01
AXA TOWER, S(068811)

Telephone: 68804888 Fax: 68804740

Email: motor.survey@axa.com.sg

Cecilia

Make/ Model : HYUNDAI AVANTE

Date: 27.05.2020

Chassis No : KMHD841CMKU933754

Vehicle No: SMP7997P

Date/Time of Accide 23.05.2020/ 1800

Reg date : 17.10.2019

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>Distorted</i>	1	\$ 658.20		\$ ✓ 658.20
2	FRONT BUMPER TOP RUBBER SEAL <i>new</i>	1	\$ 85.20		\$ ✗ 85.20
3	FRONT BUMPER TOP BRACKET RH <i>Distorted</i>	1	\$ 98.60		\$ ✗ 98.60
4	FRONT BUMPER SIGNAL LAMP RH <i>crack</i>	1	\$ 165.80		\$ ✓ 165.80
5	FRONT BUMPER RETAINER RH <i>and</i>	1	\$ 86.90		\$ ✓ 86.90
6	FRONT BUMPER AIR GUIDE RH <i>crack</i>	1	\$ 125.80		\$ ✓ 125.80
7	FRONT BUMPER SIDE STRIP RH <i>crack</i>	1	\$ 92.60		\$ ✓ 92.60
8	FRONT BUMPER SIDE COVER RH <i>crack</i>	1	\$ 98.60		\$ ✓ 98.60
9	FRONT BUMPER LOWER LIP <i>Distorted</i>	1	\$ 295.60		\$ ✓ 295.60
10	FRONT BUMPER LOWER COVER RH <i>new</i>	1	\$ 202.30		\$ ✗ 202.30
11	FRONT ENGINE UNDER COVER <i>from</i>	1	\$ 356.80		\$ 197 356.80
12	FRONT BUMPER SPONGE <i>crack</i>	1	\$ 225.60		\$ ✓ 225.60
13	FRONT BUMPER LOWER STIFFENER <i>crack</i>	1	\$ 175.20		\$ ✓ 175.20
14	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 589.50		\$ ✓ 589.50
15	FRONT BUMPER RADIATOR GRILLE <i>crack</i>	1	\$ 1,082.90		\$ ✓ 1,082.90
16	FRONT SUPPORT PANEL TOP GARNISH <i>crack</i>	1	\$ 202.50		\$ ✓ 202.50
17	FRONT SUPPORT PANEL <i>crack</i>	1	\$ 987.50		\$ ✓ 987.50
18	FRONT WASHER TANK <i>crack</i>	1	\$ 98.70		\$ ✓ 98.70
19	FRONT WASHER TANK MOTOR <i>new</i>	1	\$ 52.60		\$ ✗ 52.60
20	FRONT HEADLAMP RH <i>lit</i>	1	\$ 1,756.40		\$ ✓ 1,756.40
21	FRONT HEADLAMP BRACKET RH <i>crack</i>	1	\$ 98.60		\$ ✓ 98.60
22	FRONT BONNET <i>Distorted</i>	1	\$ 1,971.20		\$ ✓ 1,971.20
23	FRONT BONNET INSULATOR <i>new</i>	1	\$ 385.90		\$ ✗ 385.90
24	FRONT FENDER RH <i>Distorted</i>	1	\$ 985.60		\$ ✓ 985.60
25	FRONT FENDER INNER COWLING RH <i>from</i>	1	\$ 189.30		\$ ✓ 189.30
26	FRONT FENDER SIGNAL LAMP RH <i>new</i>	1	\$ 67.80		\$ ✗ 67.80
27	FRONT RIM RH <i>lit</i>	1	\$ 982.50	<i>600/50</i>	\$ ✓ 982.50
28	FRONT KNUCKLE ARM RH <i>crack</i>	1	\$ 423.50		\$ ✓ 423.50
29	FRONT WHEEL HUB BEARING RH <i>Deep</i>	1	\$ 458.90		\$ ✓ 458.90
30	FRONT STABILIZER LINK RH <i>from</i>	1	\$ 158.90		\$ ✗ 158.90
31	FRONT STABILIZER BAR RH <i>from</i>	1	\$ 298.70		\$ ✗ 298.70

32	FRONT STABILIZER BUSH RH <i>new</i>	1	\$ 48.90	\$ X 48.90
33	FRONT ABSORBER RH <i>Best</i>	1	\$ 398.70	\$ ✓ 398.70
34	FRONT ABSORBER TOP MOUNTING RH <i>new</i>	1	\$ 158.90	\$ X 158.90
35	STEERING RACK ASSY <i>Replaced</i>	1	\$ 1,023.70	\$ X 1,023.70
36	FRONT LOWER ARM RH <i>Best</i>	1	\$ 345.20	\$ ✓ 345.20
37	FRONT DOOR RH <i>Replaced</i>	1	\$ 1,831.10	\$ ✓ 1,831.10
38	FRONT DOOR STICKERS RH <i>new</i>	2	\$ 89.50	\$ ✓ 179.00
39	FRONT DOOR HINGE UPPER RH <i>new</i>	1	\$ 82.60	\$ + 82.60
40	FRONT DOOR HINGE LOWER RH <i>new</i>	1	\$ 85.20	\$ + 85.20
41	FRONT DOOR CHECKER RH <i>new</i>	1	\$ 89.10	\$ + 89.10
42	FRONT DOOR OUTER HANDLE RH <i>new</i>	1	\$ 189.30	\$ X 189.30
43	FRONT DOOR OUTER HANDLE COVER RH <i>new</i>	1	\$ 52.30	\$ X 52.30
44	FRONT DOOR CHECKER RH <i>new</i>	1	\$ 75.20	\$ X 75.20
45	FRONT DOOR OUTER MOLDING RH <i>new</i>	1	\$ 123.70	\$ X 123.70
46	FRONT DOOR WEATHERSTRIP RH <i>new</i>	1	\$ 186.30	\$ X 186.30
47	FRONT DOOR WEATHERSTRIP INNER RH <i>new</i>	1	\$ 189.60	\$ X 189.60
48	FRONT DOOR INNER TRIM RH <i>new</i>	1	\$ 756.90	\$ X 756.90
49	FRONT DOOR INNER LOCK RH <i>new</i>	1	\$ 345.60	\$ X 345.60
50	SIDE ROCKER PANEL RH <i>new</i>	1	\$ 1,764.80	\$ X 1,764.80
Total List Price Cost				\$ 21,384.30
PARTS DISCOUNT 20%				\$ 17,107.44

1311980
1097592
S.N:600

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT FENDER INNER BOWLING CLIPS <i>new</i>	1 SET	\$ 30.00	\$ ✓ 30.00
2	FRONT DOOR INNER TRIM CLIPS <i>new</i>	1 SET	\$ 30.00	\$ X 30.00
3	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ ✓ 30.00
4	FRONT NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00	\$ X 50.00
5	FRONT ENGINE UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ ✓ 30.00
6	FRONT HEADLAMP CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 10.00 30.00
7	FRONT ENGINE UNDERCOVER CLIPS <i>Replaced</i>	1 SET	\$ 30.00	\$ X 30.00
Total Special Nett Items				\$ 230.00

100

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN ,STRAIGHTENED MEMBER	\$ 1,400.00 1000
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00 1000
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 150.00
TO REMOVE / REFIT FRONT CONDENSER AND TOP UP GAS FOR SUPPORT PANEL REPLACE	\$ 120.00
LABOUR TO REMOVE / REFIT / REPLACE FRONT UNDERCARRIAGE	\$ 200.00
TO PERFORM COMPUTERISED WHEEL ALIGNMENT BEFORE / AFTER	\$ 160.00
TO PERFORM COMPUTERISED FAULT CODE CLEARANCE AND SETTLING	\$ 160.00
TO REMOVE/ REFIT WIRING CHECKS FOR HEADLAMP	\$ 300.00
Total Others Cost	\$ 940.00
GRAND TOTAL	
	\$ 21,077.44

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax : 6509 9501

2410.

Adnan Ly
 H/s 27/05/20

082p

total: 14085.92

H/s : 11.21K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: