

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHB7566H - AIG

Not Authored
21 Sep 8/801p

CANDY

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB7566H - CANDY
KL1LA69RJB078199
CHEVROLET
CHEVROLET EPICA 2.0
25.03.2017
AIG

PART			LIST	
1	1	Front Bumper	\$	<i>CM</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	<i>R</i> 295.25 ✗
3	1	Front Bumper Lower Absorber	\$	<i>Sm</i> 180.00 ✗
4	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Sm</i> 32.40 ✗
5	1	Front Bumper Lower Grille	\$	<i>Sm</i> 78.00 ✗
6	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 ✗
7	1	Front Bumper Retainer LH	\$	<i>Sm</i> 102.00 ✗
8	1	Front Bumper Retainer RH	\$	<i>Sm</i> 102.00 ✗
9	1	Front Headlamp LH	\$	<i>CM</i> 816.00 ✓
10	1	Front Fender LH	\$	<i>R</i> 837.60 ✗
11	1	Front Fender Liner LH	\$	<i>Sm</i> 47.00 ✗
12	1	Resonator (B/S Fender LH) AIR BOX	\$	<i>Sm</i> 134.67 ✗
13	1	Resonator Hose	\$	<i>Sm</i> 37.00 ✗
14	1	Radiator Grille (Grille A-Rad)	\$	<i>Sm</i> 367.00 ✗
15	1	Bonnet	\$	<i>R</i> 1,250.00 ✗
16	1	Bonnet hinge RH	\$	<i>R</i> 36.00 ✗
17	1	Bonnet hinge LH	\$	<i>R</i> 36.00 ✗
18	1	Bonnet Moulding	\$	<i>Sm</i> 161.97 ✗
19	1	Front Side View Mirror LH	\$	<i>Sm</i> 939.00 ✗

TOTAL	\$	6,788.26
10%	\$	678.83
	\$	6,109.43

Special Nett

1 1 Set Front Bumper Fastener Clip

\$

Net 30.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7566H - AIG**CANDY**

2	1 Set	Front licence plate with holder	\$	192.00 X
3	1 Set	Radiator Grille Top Cover Clip	\$	10.00 X
4	1 Set	Radiator Grille clip	\$	35.00 X
5	1 Set	Front Fender Liner Clip	\$	30.00 X
6	1	Door Sticker "Trans-cab"	\$	80.00 X
7	1	Front Tyre LH	\$	360.00 X
8	1	Front Wheel Rim LH	\$	254.00 X
9	1	Front Wheel Rim Hub Cap LH	\$	166.30 X
10	1	Front Fender Advertisement Sticker LH	\$	300.00 X

TOTAL	\$	1,457.30
TOTAL PARTS	\$	7,566.73

To Rust-Proofing Of The Affected Areas. \$ 220.00 X

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same \$ 2,800.00

Putty and Spray Painting Of The Affected
Portion. \$ 2,700.00

To Check Electrical Lighting Concerned. \$ 170.00

To check steering geometry and computer wheel
alignment \$ 220.00 X

To transfer of tire, rim and on wheel balancing. \$ 170.00 X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is one of the condition
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

REPAIR DAYS

TOTAL	\$	6,510.00
Over All Total	\$	14,076.73

10 DAYS

1 1/2 days