

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921
 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GOY BENG P A SERVICES
 126 HIGHLAND ROAD
 SINGAPORE 549198

Contact: 93987919

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE Acknowledged by Repairer

Repair Code: CLM16256 Signature:

Accident Date: 24/05/2020 Date:

Vehicle No.: GBA7947T

Model: NISSAN URVAN PANEL LWB 3.0 5DR 5MT AIRBAG 2WD

Chassis/Eng#: JN1MG4E25Z0780421/ZD30153098K

No	Description Of Parts		Qty	Unit Price	Amount
1	FRONT GRILLE <i>cracked</i>	N	1	\$ 492.90	\$ 492.90
2	FRONT GRILLE 'LOGO' EMBLEM <i>per</i>	N	1	\$ 87.90	\$ 87.90
3	FRONT LH HEADLAMP <i>3 cracked</i>	N	1	\$ 497.80	\$ 497.80
4	FRONT LH SIGNAL LAMP <i>1</i>	N	1	\$ 129.00	\$ 129.00
5	FRONT BUMPER <i>deformed</i>	N	1	\$ 629.10	\$ 629.10
6	FRONT BUMPER LH FOGLAMP <i>the one</i>	N	1	\$ 258.00	\$ 258.00
7	FRONT BUMPER LH FOGLAMP GARNISH <i>cut</i>	N	1	\$ 120.70	\$ 120.70
8	FRONT LH STEP GARNISH <i>Repair</i>	N	1	\$ 329.30	\$ 329.30

Subtotal before discount:

Percentage discount 10%:

Sub-total 1

1811.5

1630.35

\$ 2,544.70
 \$ 254.47
\$ 2,290.23

9	FRONT GRILLE CLIPS - SET <i>new</i>	S	1	\$ 30.00	\$ 30.00
10	FRONT LH HEADLAMP CLIPS - SET <i>new</i>	S	1	\$ 30.00	\$ 30.00
11	FRONT BUMPER CLIPS - SET <i>new</i>	S	1	\$ 50.00	\$ 50.00
12	FRONT LH STEP GARNISH CLIPS - SET <i>the one</i>	S	1	\$ 30.00	\$ 30.00

Subtotal before discount:

Percentage discount 0%:

Sub-total 2

Parts-total

60

\$ 140.00
 0.00
 \$ 140.00
\$ 2,430.23

LABOUR

1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	\$ 80.00
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	\$ 600.00
3	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	\$ 500.00
4	To apply anti-rust chemical on repaired and replaced panel.	\$ 60.00
Labour total		\$ 1,240.00
Parts & Labour total		\$ 3,670.23

610

total: 2300.35

03 Days + 1.8K