



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

TPAIG

Khanchar

LKK

KNAFU411MAS283971

DATE: 25/05/2020

REF: UAPL1385

REPAIR ESTIMATE TO THE KIA CERATO FORTE NO: SJY6286C

- 1 REAR BUMPER FACE *Deformed*
- 1 REAR BUMPER REINFORCEMENT *cracked*
- 2 REAR BUMPER REINFORCEMENT BRACKET @ 85 RH *bet*
- 2 REAR BUMPER SIDE METAL BRACKET @ 22 *new*
- 2 REAR BUMPER SIDE RETAINER BRACKET @ 35 *new*
- 1 REAR BUMPER BLACK SPONGE *cracked*
- 10 REAR BUMPER CLIPS @ 3 *new*
- 1 REAR TAIL END PANEL *Dented*
- 2 REAR TAIL LAMP ASSY @ 263 RH *cracked*
- 1 REAR BOOT ASSY *cracked*
- 1 REAR BOOT LOCK *new*
- 1 REAR BOOT LOCK ACTUATOR } *new*
- 1 REAR BOOT STRIKER }
- 1 REAR BOOT KIA EMBLEM }
- 1 REAR BOOT CERATO EMBLEM }
- 1 REAR BOOT FORTE EMBLEM }
- 1 REAR BOOT LIMITED EMBLEM }
- 2 REAR BOOT LAMP @ 135 *new*
- 2 REAR BOOT HINGES @ 65 *new*
- 1 REAR BOOT WEATHERSTRIP *ut*
- 2 REAR FENDER INNER SIDE LINING GARNISH @ 275 RH *torn*
- 1 REAR FLOOR PANEL *Repr*
- 1 REAR EXHAUST PIPE *new*
- 2 REAR EXHAUST PIPE MOUNTING @ 28 *new*
- 1 REAR AIR OUTLET GARNISH *new*
- 1 REAR SPARE WHEEL TOP COVER BOARD *Deformed*
- 1 REAR PANEL LINING GARNISH *Deformed*

607 ✓
356 ✓
170 85
44 x
70 ✓
134 ✓
30 ✓
482 ✓
526 263
747 ✓
113 x
205 x
28 x
32 ✓
38 ✓
37 ✓
35 ✓
270 x
130 x
98 ✓
550 275
633 x
686 x
56 x
39 x
189 ✓
92 ✓

3570
3213

SPECIAL NETT:-

- 1 REAR REVERSE SENSOR *Dented*
- 1 REAR BUMPER LOWER SPOILER *cracked*

\$ 280.00 *200*
\$ 950.00 *650* 850

LABOUR CHARGES:-

- TO DISM/RENEW REAR REVERSE SENSOR
- TO DISM/RENEW REAR EXHAUST BOX
- TO SPRAY UNDERCOATING IN REPAIR
- TO DISM/REPAIR DAMAGED PORTION
- TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
- TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 80.00 50
\$ 200.00 x
\$ 150.00 60
\$ 180.00 30
\$ 1,200.00 800
\$ 1,000.00 800

1740

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5803

W/S: HK (Nett Value)
06 Days